



PO Box 9084, HARKAWAY VIC 3806 |

Personal Information

| Email: [info@fairfireservices.com.au](mailto:info@fairfireservices.com.au) | ABN 60 900 174 581

## **FIRE FIGHTING DIAGNOSTIC INSPECTION REPORT**

1.	PREMISES	Bayview Rd & Outlook Rd, McCrae VIC 3938
2.	REPORT NO	T - 27219
3.	DATE INSPECTED	12 April 2025
4.	ABBREVIATIONS	
	4.1 HYDRANTS	IN - GROUND BALL HYDRANT
	4.2 HOSE REELS	N/A
	4.3 HYDROSTATIC TEST	NIL
	4.4 PUMP APPLICANCE	NIL
	4.5 DISPENSATIONS/309	NIL ADVISED
	4.6 SPRINKLER PROTECTED	N/A
	4.7 ESTIMATED FLOOR AREA	N/A
	4.8 DATE INSTALLED	N/A
	4.9 GRADE OF TAPPING	3
	4.10 LEVELS ABOVE GROUND FLOOR	N/A
	4.11 CLASS OF BUILDING	N/A
	4.12 DISCHARGE TANKS USED ONSITE	NO
	4.13 ZONES	1
	4.14 PASS OR FAIL	
5.	FIRE MAIN	
	5.1 FIRE MAIN (where visible or advised)	N/A installed onsite.
	5.2 STREET HYDRANT	In - ground ball Street hydrant installed in accordance with the local water authority, I identified by street reflector.
6.	INSTALLATIONS	



PO Box 9084, HARKAWAY VIC 3806 |

Personal Information

| Email: info@fairfireservices.com.au | ABN 60 900 174 581

**6.1 HYDRANTS**

N/A risers installed onsite.

**7. PRESSURES RECORDED**

Pressure/Flow tests were conducted in accordance with the guidelines of Australian Standard 2419.1 - 2005 and accepted industry methods.

**7.1 STATIC**

750 KPA

**7.2 FLOWS****Nozzle Size** 25mm**Hydrant Type** Feed Hydrant**Hydrant** Most Disadvantaged Hydrant**Required Pressure** Minimum 10 LPS**Hydrant Single Flow** 500 KPA at 15.52 LPS**Required Pressure** Minimum 20 LPS**Hydrant Dual Flow** 280 KPA at 23.23 LPS

THE HYDRANT WAS TESTED, AND THE PRESSURES RECORDED WERE CALCULATED USING THE HAZEN-WILLIAMS FRICTION LOSS EQUATION.

**8. LOCATION OF EQUIPMENT**

Drawings were not available onsite to determine the positions of fire equipment.

**9. COMMENTS**



PO Box 9084, HARKAWAY VIC 3806 |

Personal Information

| Email: [info@fairfireservices.com.au](mailto:info@fairfireservices.com.au) | ABN 60 900 174 581**9.1 COMMENTS / PICTURES****Site Observation,**

During my on-site assessment, I noted a discrepancy in the pressure readings. With a static pressure of 750 kPa and a dual flow pressure of 280 kPa, it suggests that there may be an obstruction or issue affecting the flow. Based on my experience, a static pressure of 750 kPa should typically yield a flow pressure greater than 400 kPa.

**\*Possible Causes: \***

1. Partly shut valve in the area, restricting flow
2. Leak in the street mains, hindering flow

Further investigation is recommended to determine the root cause and implement necessary corrections.

Under practice note 38 BCC indicates,

Any system with (other pipe work to be hydrostatically tested to 700kpa or mains pressure.), it was noted on the day of testing the system had a hydrostatic pressure of 750kpa in the mains.

**9.2 TESTING**

This inspection covers the items specified in AS1851-2012 and AS2419.1 - 2005.

Inspection and tests carried out by Mr Ronny Allard and Daniel Towt.

**9.3 GAUGE CALIBRATION**

All gauges used in this test are performance calibrated and checked by Ambit Instruments PTY LTD, NATA Accredited Laboratory no: 3103, gauge has NATA endorsed certificate number 1807498.

**APPROVED INSPECTOR**

Irrelevant &amp; Sensitive

**Ronny Allard**  
**Fair Fire Services**  
**VBA Licence Number 102569**  
**Dated 12 April 2025**

