| Montage Task Number | Action Taken Category – Class - Type | Department | Date Created | a. a description of any roadworks or excavation work performed by SEW, including the purpose and outcome of such works; | b. the location of the works. | c. the date those works were performed; and | d. any photographs depicting the works themselves or the location before and after the works were performed. |
|------------------------|---|----------------------|------------------|--|--|---|--|
| 1297589/001 | Plumbing Sewer - Sewer Drain - Inspection | SEW PriorityPlumbing | 27/12/2024 10:42 | Purpose: - Customer request for blocked plumbing. Outcome: - Plumber attended and found the blockage in South East Water's Property Connection Branch and cleared the blockage. | 139 BAYVIEW ROAD, MCCRAE VIC 3938 | 27/12/2024 | See folder 1297589 for Montage extracts |
| 1297589/002 | Sewer Network - Property Connection Branch - Unblock | SEW PriorityPlumbing | 27/12/2024 12:26 | Purpose: - Task created to capture blockage against South East Water's Asset. Outcome: - Blockage recorded. | 139 BAYVIEW ROAD, MCCRAE VIC 3938 | 27/12/2024 | |
| 1304490/001 | Sewer Network - Sewer Pipe - Digout | ServiceStream Sewer | 23/01/2025 15:35 | Purpose: - The scope of our works is: - Excavate a shaft to the depth of embedment of the sewer main (approximately 2.5m deep). Observe and measure the flow within the shaft. If required, install a trench stop and run a drainage pipe to the nearby Council stormwater pit located outside 1 Charlesworth Street. Outcome: - Observations were made with Mornington Peninsula Shire Council representatives, trench stop installed and excavation backfilled. | 3 CHARLESWORTH STREET, MCCRAE VIC 3938 | 24/01/2025 – 28/01/2025 | See folder 1304490 for Montage extracts |
| 1304490/002 | Sewer Network - General - Operational Support | SEW Sewer | 24/01/2025 11:17 | Purpose: - To record observations from the site inspection and capture photos. Outcomes: - Observations captured in Task Story. | 3 CHARLESWORTH STREET, MCCRAE VIC 3938 | 24/01/2025 – 28/01/2025 | |
| 1304490/003 | Sewer Network - Sewer Pipe - CCTV Inspection and Clean | ServiceStream Sewer | 28/01/2025 15:15 | Purposes: - Internally CCTV 3 sewer reticulation lines for structural and serviceability assessment. Outcome: - The CCTV was carried out on the lines with the lines assessed by South East Water. | 3 CHARLESWORTH STREET, MCCRAE VIC 3938 | 29/01/2025 | |
| 1304490/004 | Roadworks - Roadway - Reinstatement | Service Stream RI | 31/01/2025 09:33 | Purpose: - To reinstate the road and kerb and channel from the excavation works. Outcome: - 6 sqm of asphalting was completed along with 2.1m of concrete kerb and channel. | 3 CHARLESWORTH STREET, MCCRAE VIC 3938 | 12/2/2025 – Kerb and Channel reinstatement 18/2/2025 – Asphalt reinstatement | |
| 1300775/001 | Sewer Network - Sewer Pipe - Unblock | Downer Sewer | 10/01/2025 13:19 | Purpose: - To investigate and clear a sewer blockage in the reticulation sewer. Outcome: - Cleared blockage in the 150mm VC sewer line | 36 COBURN AVENUE, MCCRAE VIC 3938 | 10/01/2025 | See folder 1300775- 001 for Montage extract |
| 1338997/001 | No Work Cancelled - No Work Cancelled - No Work Cancelled | ServiceStream Sewer | 24/04/2025 12:25 | Purpose: - To raise 3 maintenance structures to ground level for access. Outcome: - Task CANCELLED as per duplicate request. | 38 COBURN AVENUE, MCCRAE VIC 3938 | - | See folder 1338997 for Montage extracts |
| 1338997/002 | Sewer Network - Manhole - Cover alteration | ServiceStream Sewer | 24/04/2025 12:31 | Purpose: - To locate and raise 3 Maintenance Structures. Outcome: - 2 of the 3 Maintenance Structures raised to surface. | 38 COBURN AVENUE, MCCRAE VIC 3938 | 2/5/2025 | |
| 1339645/001 | Sewer Network - Manhole - Alteration | ServiceStream Sewer | 28/04/2025 10:54 | Purpose: - To raise Maintenance Structure to surface. Outcome: - Maintenance structure NEP39-509 was raised to surface 250mm. | 26 COBURN AVENUE, MCCRAE VIC 3938 | 2/5/2025 | See folder 1339645- 001 for Montage extract |
| 1340050/001 | Sewer Network - Manhole - Cover Grease & Grind | ServiceStream Sewer | 29/04/2025 15:21 | Purpose: - To open Maintenance Structure NEP39-506. Outcome: - Access on obtained and a clean of the Maintenance Structure was carried out. | 11 COBURN AVENUE, MCCRAE VIC 3938 | 30/4/2025 | See folder 1340050- 001 for Montage extract |
| 1341250/001 | Sewer Network - Manhole - Clean | Downer Sewer | 4/05/2025 9:36 | Purpose: - Maintenance Structure NEP39-506 to be cleaned. Outcome: - Maintenance structure was cleaned. | 11 COBURN AVENUE, MCCRAE VIC 3938 | 6/5/2025 | See folder 1341250- 001 for Montage extract |
| 1341738/001 | Sewer Network - Manhole - Alteration | ServiceStream Sewer | 6/05/2025 12:16 | Purpose: - To raise Maintenance Structure NEP42-544 to surface. Outcome: - Maintenance structure NEP42-544 was raised to surface 350mm. | 27 COBURN AVENUE, MCCRAE VIC 3938 | 22/5/2025 | See folder 1341738- 001 for Montage extract |
| 1299529/001 | Sewer Network - Sewer Pipe - Investigation | ServiceStream Sewer | 5/01/2025 21:46 | Purpose: - To investigate a possible sewer reticulation stoppage. Outcome: - Investigated the sewer with CCTV and no signs of sewer stoppage and/or sewer odour. | 3 PENNY LANE, MCCRAE VIC 3938 | 5/1/2025 | See folder 1299529 for Montage extract |
| 1299529/002 | Sewer Network - Manhole - Cover | ServiceStream Sewer | 6/01/2025 14:36 | Purpose: - To open Maintenance Structure NEP39-582. Outcome: - Replaced Maintenance Structure NEP39-582 cover in | 14 HENRY COURT, MCCRAE 3938 (1 | 7/1/2025, 21/1/2025 – | |

| | alteration | | | | CHARLESWORTH | | |
|-------------|--|---------------------|------------------|--|--|---|---|
| | alteration | | | | STREET, MCCRAE VIC 3938) | | |
| 1299529/003 | Sewer Network - Sewer Pipe - CCTV Inspection and Clean | ServiceStream Sewer | 24/01/2025 09:15 | Purpose: - Internally CCTV 3 sewer reticulation lines for structural and serviceability assessment. Outcome: - The CCTV was carried out on the lines with the lines assessed by South East Water. | 14 HENRY COURT, MCCRAE 3938 (1 CHARLESWORTH STREET, MCCRAE VIC 3938) | 11/2/2025 | |
| 1299529/004 | Roadworks - Roadway - Reinstatement | Service Stream RI | 31/01/2025 09:45 | Purpose: - To reinstate the road around Maintenance Structure after the cover replacement. Outcome: - 1 sqm of asphalting was completed around the cover. | 14 HENRY COURT, MCCRAE 3938 (1 CHARLESWORTH STREET, MCCRAE VIC 3938) | 24/2/2025 | |
| 1303404/001 | Sewer Network - Sewer Pipe - CCTV inspection | ServiceStream Sewer | 20/01/2025 14:49 | Purpose: - CCTV inspection of the sewer reticulation. Outcome: - The CCTV was carried out and assessed by South East Water. | 16 PROSPECT HILL ROAD, MCCRAE VIC 3938 | 20/1/2025 | See folder 1303404- 001 for Montage extract |
| 1337352/001 | Sewer Network - Sewer Pipe - CCTV Inspection and Clean | ServiceStream Sewer | 16/04/2025 15:45 | Purposes: - Internally CCTV 39 sewer reticulation lines for structural and serviceability assessment. Outcome: - The CCTV was carried out on the lines with 37 lines assessed by South East Water. | 27 COBURN AVENUE, MCCRAE VIC 3938 (Task includes assets in Prospect Hill Road, Coburn Avenue, Waller Place, Charlesworth Street) | 16/4/2025, 22/4/2025 – 24/4/2025, 28/4/2025 – 2/5/2025, 5/5/2025 – 6/5/2025 | See folder 1337352 for Montage extracts |
| 1337352/002 | Sewer Network - General - Operational Support | SEW Sewer | 29/04/2025 08:59 | Purpose: - To record times from the site inspection. Outcomes: - Task not used. | 27 COBURN AVENUE, MCCRAE VIC 3938 (Task includes assets in Prospect Hill Road, Coburn Avenue, Waller Place, Charlesworth Street) | - | |
| 1337352/003 | Sewer Network - Sewer Pipe | ServiceStream Sewer | 8/05/2025 15:24 | Purposes: - Internally CCTV 2 sewer reticulation lines for structural and serviceability assessment. Outcome: - Not completed to date. Needs to be scheduled with property owner for access. | 5 PROSPECT HILL ROAD, MCCRAE VIC 3938 | - | |
| 1337352/004 | Sewer Network - Sewer Pipe | ServiceStream Sewer | 22/05/2025 09:32 | Purposes: - Please excavate and point repair 150mm VC sewer asset. Outcome: - Not completed to date. Needs to be scheduled. | 7 HENRY COURT, MCCRAE 3938 | - | |
| 1337352/005 | Sewer Network - Sewer Pipe | ServiceStream Sewer | 5/06/2025 14:06 | Purposes: - to patch the following sewers to prevent root ingress: 1052155978 - Patch at 10.8m U/S of NEP39-566; 1052156026 - Patch at 36m D/S of NEP42-515; 1052155962 - Patch at 37.7m D/S of NEP39-514; 1052155976 - Patch at 22.9m U/S of NEP39-577; 1052160456 - Patch at 1.0m D/S of NEP39-520; Outcome: - Not completed to date. Needs to be scheduled. | 38 Coburn Ave 6-8 Prospect Hill Road 32 Coburn Ave 38 Coburn Ave Bayview Road | - | |
| 1295094/009 | Sewer Network - Sewer Pipe - Clean | ServiceStream Sewer | 22/01/2025 15:22 | Purpose: - Clean sewer reticulation main as signs of restricted flow. Outcome: - Cleaned line and removed tree roots from the sewer. | 4 WALLER PLACE, MCCRAE VIC 3938 | 28/1/2025 | See folder 1295094- 009 for Montage extract |
| 1341266/002 | Sewer Network - General - Miscellaneous | ServiceStream Sewer | 5/05/2025 8:27 | Purpose: - To open Maintenance Structure NEP39-517. Outcome: - Grinded and greased the cover to sit flush when closed. | 3 WALLER PLACE, MCCRAE VIC 3938 | 6/5/2025 | See folder 1341266- 002 for Montage extract |
| 1107857/003 | Sewer Network - Property Connection Branch - Reline | Downer Sewer | 2/08/2023 11:09 | Purpose: - Structurally reline the Property Connection Branch. Outcome: -cctv inspect and record pre clean, clean and prep drain for relining, Record post clean cctv and install 1800mm PCB liner in PVC. | 6 VIEW POINT ROAD, MCCRAE VIC 3938 | 31/3/2025 | See folder 1107857- 003 for Montage extract |