
Leak Report



17 Charles Street McCrae Victoria 3938 Australia



CREATED

- ① 07/05/2025, 9:37:39 am
- by Morgan Williams

LOCATION

○ -38.350191, 144.933657

PROJECT

Service Stream

Leak Address	McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Customer Leak
Flow Rate (L/min)	20
Has the leak been called in by DS Technician?	No
Job Ref	LD0012
Leak Visible	Yes



Comments

2hr travel 2hr onsite

Arrived at property and meter was switched off. I knocked on property to inform the customer that I was carrying out leak detection, but no one was at the property. I turned on the meter so I could carry out the work.

Probe down close to the back of the meter and had noise present but was just picking up the meter. The service then goes across the driveway and up to the property and then through the property, so there was expose pipe work going up the property, and that had very good noise on it.

Went around the have of the property and there wad couple of outside taps to sound and I narrowed down the leak between the first two outside taps. I then had a look around the first tap, and I walked a bit further around and could hear a leak noise, and then I saw water running down bank.

Please see the photos down below of location and leak, I have marked up the leak with a stick and sprayed it blue. I have isolated the supply again.

Photo

DETECTION

