
Leak Report



23 Flinders Street McCrae Victoria 3938 Australia



CREATED

① 07/02/2025, 11:21:33 am

by Morgan Williams

LOCATION

PROJECT

South East Water

Lear Address	McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Valve
Flow Rate (L/min)	0.5
Has the leak been called in by DS Technician?	No
Job Ref	NA
Leak Visible	No
Comments	Suspected leak on valve. Picking up noise on valve and hydrant next to it hasn't got much noise on it. Managed to get the valve cover off, and there's no leak showing, but it's very saturated/wet in valve chamber when probing with FSB.



Photo





