
Leak Report



33 Wattle Place McCrae Victoria 3938 Australia



CREATED

① 09/05/2025, 8:51:25 am

by Stuart Haggett

LOCATION

PROJECT

☐ Service Stream

Leak Address	33 Wattle Place McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Customer Leak
Flow Rate (L/min)	5
Has the leak been called in by DS Technician?	No
Job Ref	LD00011
Leak Visible	No



Comments

Arrived onsite, met with owner & he showed me where he thinks leak is In rear bungalow

Can hear water hissing & wet patch next to front door/step/wall. Can also feel fine spray of water.

Behind wall is laundry sink, sounded both taps (hot & cold) & cold tap is screaming. Confirmed that leak/burst is on cold tap line, somewhere behind wall. Looks like asbestos cement/wall panels

Suggest they organise plumber to cut hole in wall to better pinpoint/find leak

Photo



