
# Leak Report



## 37 Somers Avenue McCrae Victoria 3938 Australia



### **CREATED**

- ① 03/06/2025, 2:13:35 pm
- by Stuart Haggett

### **LOCATION**

© -38.360846, 144.931402

#### **PROJECT**

☐ Service Stream

	McCrae Victoria 3938 Australia
Zone	South East Water ▶ Parkes St Tank Zone
Leak Asset Type	Hydrant
Flow Rate (L/min)	0.3
Has the leak been called in by DS Technician?	No
Leak Visible	No
Comments	Ground hydrant leaking from ball







