

Leak Report



Bayview Rd McCrae VIC 3938 AU



CREATED

03/06/2025, 10:46:04 am

by Scott Grace

LOCATION-38.348946, 144.939569**PROJECT**Service Stream

Leak Address	Bayview Rd McCrae VIC 3938 AU
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Tracing
Flow Rate (L/min)	0.1
Has the leak been called in by DS Technician?	No
Job Ref	1347304/001
Leak Visible	No

Comments

Met surveyor/SEW on-site to attempt to trace metallic and PVC pipelines.

Successfully traced metallic pipeline which crossed Bayview Road and run down near the Fence-line to valves/hydrants.

Struggled to pick up the PVC pipeline using the AML tool. Would require Vac truck to prove what was being picked up with the AML tool.

Another option to trace the PV pipeline would be to use GPR, dependent on soil type, depth of main etc.

Photo

