## 10-12 View Point Road Inspection 27/02/2025

- Dave request entry to the dwelling for following reasons: inspect Fridge and Dilapidation
   Report
- Consent given by Bronwyn
- Fridge appears to be clean and neat

## **PICTURES**









Figure 3 Linen Cupboard



Figure 4 East Bedroom P1



Figure 5 East Bedroom P2



Figure 6 East Bedroom 3



Figure 7 East Bedroom 4



Figure 8 East Bedroom 5



Figure 9 East Bedroom 6



Figure 10 East Bedroom 7





Figure 12 East Bedroom 9



Figure 13 East Bedroom 10



Figure 14 Front Landing 1



Figure 15 Front Landing 2



Figure 16 Hall outside ground floor bedroom




Figure 17 Hall outside ground floor bedroom



Figure 18 Front landing 3



Figure 19 Master Bedroom 1



Figure 20 Master Bedroom 2




Figure { SEQ Figure \\* ARABIC }1 Master Bedroom 3



Figure 2{ SEQ Figure \\*
ARABIC } Master Bedroom 5



Figure 2{ SEQ Figure  $\*$  ARABIC } Master Bedroom 6



Figure 3{ SEQ Figure \\* ARABIC } - Laundry



Figure 38 Under the House




Figure 2{ SEQ Figure \\* ARABIC } Master bedroom 7



Figure { SEQ Figure \\* ARABIC } wall under the house that has been dug out



Figure 28 North Bedroom 1



Figure 29 North Bedroom 2



Figure 27 Master Bedroom 8

Figure 30 Cellar



Figure 31 Kitchen



Figure 33 Kitchen 2



Figure 34 Kitchen 3



Figure 35 Bar

Unreinforced stone word under hous
------------------------------------

- Lots of soil removed, orange line shows crack and where the outside soil line is.

Garage – has "\$21,000" worth of items missing. Only power tools in there are an old DeWalt drill and a soldering iron.

Gerry requests to come back to do an internet upgrade to improve cameras

Dave inquires about 2022 slide irrigation

- Old pipes only on the top section
- Old septic system could possibly be transporting water down the escarpment (Not decommissioned correctly)