net name	tk axim id assettype ti		tk datecompleted	tk categorth category	tk class tk classdescr		tk codedescr	tik status	tk descr	Sk note		quantitrik_unitofmeasure
MARGARET STREET	215575.0545 Network	11/19/20 0:00		UPAVT URT01 - Gravel Patch	LS Lump Sum		URT01 - Gravel Patch	COMPLETED	from where you finished last week to the concrete drive of number \$	M# 2257021 Brush over to the concrete driveway of number B as Margnet St actually swings around past number B's driveway and turns into a walking track.	28D	SDSQM
PENNY LANE	215310.0545 Network	6/2/20 0:00	6/10/20 0:00	UPAVT URT01 - Gravel Patch	LS Lump Sum	URT01	URT01 - Gravel Patch	COMPLETED	Penny Lane West	MM 2203218 Gravel patch potholes as needed - allow little topper load of rock	28D	80SQM
PENNY LANE	478.0571 Network	1/6/21 0:00	1/15/21 0:00	PPR RPT01 - Repair Pothole	LS Lump Sum	82701	RPT01 - Repair Pothole	COMPLETED	car park opp Penny lane Mccrae	car park opp Penny Lane drive in to car park the first parking spot on your right 1mt x2.5 were edge has broken away merit 2278556	14D	4SQM
PENNY LANE	6750.0593 Network	8/16/21 0:00	8/20/21 0:00	2022 PGU01 - Gravel Patch	LUMP_SUILump Sum	PGU01	PGU01 - Gravel Patch	COMPLETED	On Penny Lane west 20m in from Pt Nepean Rd	Bobcat gravel patching required to fill potholes . 3 or 4 buckets required .	28D	SOLINM
PENNY LANE	6412.4162 Network	1/25/22 12:19	1/25/22 12:19				RLCD1 - Hand Waste Collection: Unidentifiable	COMPLETED	beach box 8-9, McCrae, opposite penny lane	M#2411498 Marquee removed	3D	0.25 SQM
PENNY LANE	222668.0552 Network	7/9/22 12:17	8/9/22 9:06		LUMP_SUKump Sum		PGU01 - Gravel Patch	COMPLETED	Penny Lane West McCrae	Add rock to laneway when dryer. Large potholing occurring, M2464359	28D	100LINM
PENNY LANE	1954.0569 Network	11/15/22 16:29	11/21/22 16:30		LUMP_SUKump Sum		MEC01 - Make Safe	COMPLETED	Penny Lane McCrae	MW2505684 Call out id 31685288 A/hrs attended location and SES and Shine were already onsite, rifa req	2H	1105
PROSPECT HILL ROAD	2035.0593 Network	2/20/20 0:00	3/4/20 0:00		LS Lump Sum		RPT01 - Repair Pothole	COMPLETED	1 x pothole beside kerb o/s # 14 Prospect Hill rd .	NULL	14D	0.85QM
PROSPECT HILL ROAD	643.0571 Network	4/14/21 0:00	4/19/21 0:00		LUMP_SUKump Sum		PPR01 - Repair Pothole	COMPLETED	Prospect Hill Rd Mccrae	Repair pothole O/S #1 merit #2317841	14D	15QM
THE EYRIE	243.0591 Network	1/27/20 0:00		BWALK BWT09 - Provisional Works			BWT09 - Provisional Works	COMPLETED	The Dyrie McCrae - Stairs	Remove the rotted and falling timber edge strips to the concrete steps & replace with new timbers	SY	BITEM
VIEW POINT ROAD	422.06 Network	7/31/21 0:00	7/31/21 0:00	2001 MEC01 - Make Safe	LUMP_SUKump Sum			COMPLETED	5 View Point Road MCCRAE	After Hours Callout ID: 28321541 GR attended assessed site and phoned through to Parks to attend M# 2351120	2H	1105
VIEW POINT ROAD	578.0613 Network	5/26/22 10:32	6/9/22 11:35		LUMP_SUNump Sum		PPR01 - Repair Pothole	COMPLETED	View point Mc rae	please fill speed hump were meets the kerb	14D	SSQM
VIEW POINT ROAD	598.0613 Network	6/10/22 6:59	6/29/22 9:24	2010 PPR - Pothole Repair	LUMP_SUNump Sum	99901	PPR01 - Repair Pothole	COMPLETED	View point road Mc Crae	Were speed hump has been cut , please add ash to fill up the gap /ring Neil	14D	250M

				ef_datecompletedef		def_stass	def_classificity co.			an def_conditiondescr	def_status	del_desar	def_nate		Equantities untofereas
MA	CAMETERNIT	Network.		11/04/30 D 00 UP I		13	Lump SumURCO				COMPLETED	from where you finished last week to the concrete drive of number 8		280	103QM
PER	EV LANE	Network.		6/50/33 D 30 UP I		13	Lump SumURDS			Puthole - Depth > 35mm for 32 Percentage	COMPLETED	PennyLane West	MR 220000 Gravel patch patch patch patch patch patch patch patch patch stopper load of rack	280	MOROM
PER	ev LANE	Network.		1/55/21 0 00 PPR		13	Lump SumRPOS			Depth >50mm Diameter >300mm	COMPLETED	car park app Penny lane Microse	car park upp Penny Lane drive in to car park the first parking spot on your right 1xit x2.5 were edge has broken away ment 2278556	160	41QM
PER	EV LANE	Network.	8/34/21 0:00		2022 Any Potholes Corrugations Scouring Rulling or					Defects must not exceed 35mm in depth for >52 Percentage of area of formation.	COMPLETED	On Penny Lane west 20m in from Pt Nepean Rd	Bolicial gravel publishing required to fill publishes. I or 4 business required .	280	SOUNM
					2028 NLC - Street and Drain Litter Collection	DUMP_SUM							NO.		
PER		Network.	7/9/22 12:17		2022 POU - Grading Unswided roads	UUMP_SUM		Any Pothales, Corrugations, Scouring, Rulling or Showing.		Defects must not exceed 35mm to depth for >32 Percentage of area of formation.	COMPLETED	Penny Lane Wed McCrise	Add rick to laneway when dryer, Large poliholog occurring, M2060338	280	SECURM
					2005 MEC - Call Dull Service	DUMP_SUM		Any self-out services that are contactable (public or anyone etier) 25 hrs. a day, year round.			COMPLETED	Penny Lane MiCrise	MEDICINE Call out of ESSECEE Afric attended location and SEL and Shire were already unable, of a req.	24	110%
	SPECT HELL ROSS					13	Lump SumRPOS			Depth >50mm Diameter >300mm	COMPLETED	Expothele beadwhelb s/LEEE ProspectMITHE.		160	MDEKO
PEC	SPECT HELL ROSID	Network.	4/14/21 0:00		2003 Any Potholes or Small Delanorations.	DUMP_SUM			PPRCLCS	Depth >50mm or Lateral Dimension >200mm. Bille Lanes >20mm	COMPLETED	Progest HEM Misse	Repair puthole Offile I merit #21917861	34D	19QM
					SK Provinced Works			Provisional Works					Remove the ratted and falling timber edge strips to the concrete days: replace with new timbers.		
VIII	POINT ROAD	Network.	8/31/21 0:00		2000 Any call out senaces that are contactable (public-						COMPLETED	5 View Point Road MCCRAE	After Hours Callust ID: 28321541 Off attended assessed site and phoned through to Parks to attend MR 2351120	24	110%
			1/24/22 10:11		2013 PPK - Puthale Repair	DUMP_SUM				Depth >50mm or Lateral Dimension >200mm. Bille Lanes >20mm	COMPLETED	Viewpoint Microe	please fill speed hump were meets the barb	34D	13QM
VIII	POINT ROAD	Network.	6/30/22 6:56	6/28/22 9:24	2013 PPK - Puthale Repair	UUMP_SUM	Lump SumPPROS	Any Polhales or Snad Delaminations	PPROLOS	Depth >50mm or Lateral Dimension > 200mm. Bille Lanes > 20mm	COMPLETED	View point road Mc Crae	Were speed hump has been cut, please add ach to fill up the gap, fing Net!	160	21QM

SELECT Net.net_name,Tsk.*

FROM [Nextgen_Contracts_Data].[dbo].[dm_roads_task] Tsk
inner join [SLR_Contract_Prod].[dbo].[network] Net
on Tsk.a float00 = Net.axim id

on isk.a_noatoo = Net.axiin

Where

Net.net_locality = 'MCCRAE'

and Net.net_name in('PENNY LANE','PROSPECT HILL ROAD','THE EYRIE','VIEW POINT ROAD','MARGARET and tk_datecompleted between '2019-11-01 00:00:00.000' and '2022-11-30 00:00:00.000' and tk_Axim_id not in(4528.4162,3898.4162,1091.4162,3969.4162,1495.4162,5388.4162,5405.4162) order by Net.net name,tk datecompleted

SELECT Net.net_name,Tsk.*

FROM [Nextgen_Contracts_Data].[dbo].[dm_roads_task] Tsk inner join [SLR_Contract_Prod].[dbo].[network] Net on Tsk.a_float00 = Net.axim_id

Where

Net.net_locality = 'MCCRAE'

and Net.net_name in('PENNY LANE','PROSPECT HILL ROAD','THE EYRIE','VIEW POINT ROAD','MARGARET and tk_datecompleted between '2019-11-01 00:00:00.000' and '2022-11-30 00:00:00.000' and tk_Axim_id not in(4528.4162,3898.4162,1091.4162,3969.4162,1495.4162,5388.4162,5405.4162) order by Net.net_name,tk_datecompleted

SELECT Net.net name,Tsk.*

FROM [Nextgen_Contracts_Data].[dbo].[dm_roads_task] Tsk inner join [SLR_Contract_Prod].[dbo].[network] Net on Tsk.a_float00 = Net.axim_id

Where

Net.net_locality = 'MCCRAE'

and (tk_Descr like '%Landslip%' or tk_Descr like '%Landslid%')

and tk_datecompleted < '2022-11-30 00:00:00.000'

and tk_Axim_id not in(4528.4162,3898.4162,1091.4162,3969.4162,1495.4162,5388.4162,5405.4162) order by Net.net_name,tk_datecompleted

select * from [SLR Contract Prod].[dbo].[network]

Where net_name in('PENNY LANE','PROSPECT HILL ROAD','THE EYRIE','VIEW POINT ROAD','MARGARET S

STREET')

STREET')

TREET')