

Message

From: Swain, Charles [Charles.Swain@sew.com.au]
Sent: 14/01/2025 10:14:20 AM
To: Lloyd, Tim [Tim.Lloyd@sew.com.au]; Ramamurthy, Prerna [Prerna.Ramamurthy@sew.com.au]
Subject: Landslide at Viewpoint Rd, McCrae

Importance: High
Flag: Follow up

Hi Tim and Prerna,

Over the last 10 days we have been working with the customers and Morn Pen Council to investigate the source of water coming out of the ground at multiple locations that has caused a land slip at 10 Viewpoint Rd, McCrae. This included leak detection of the whole area, review of pressure and flow data from trends at the zone pump station and water quality sampling of 3 of the points where water has been surfacing. We have yet to conclude these investigations, as further leak detection is currently being undertaken further north, however at this stage our investigations are concluding that the water is not from the SEW Water Network.

We did identify 2 leaks across the highway which have now been repaired but these were overflowing into the stormwater drain and not going into the ground. Once our investigations have been concluded I will be preparing a summary report of our activities and findings.

Here is a link to the news article:

[House falls down cliff on Mornington Peninsula](#)

Let me know if you require further information. Also, do you want me to Share with comms and our stakeholder team?

Thanks,

Charles Swain
 Water Maintenance Manager



WatersEdge 101 Wells Street
 Frankston VIC 3199

T +613 9552 3494

M Personal Data



South East Water proudly acknowledges the Traditional Owners of the land on which we work and live, and pay respect to their Elders past, present and emerging. We acknowledge their songlines, cultural lore and continuing connection to the land and water. We recognise and value the rich cultural heritage and ongoing contributions of Aboriginal people and communities to our society in Victoria.