
Leak Report



115 Bayview Road McCrae Victoria 3938 Australia



CREATED

- ① 07/02/2025, 10:35:20 am
- by Stuart Haggett

LOCATION

© -38.353801, 144.931587

PROJECT

South East Water

Leak Address	McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Hydrant
Flow Rate (L/min)	0.2
Has the leak been called in by DS Technician?	No
Job Ref	NA
Leak Visible	Yes
Comments	Small leak on hydrant ball



Photo

