Leak Report



17 Cook Street McCrae Victoria 3938 Australia



CREATED

- ① 06/06/2025, 1:17:07 pm
- by Stuart Haggett

LOCATION

○ -38.359543, 144.936674

PROJECT

Service Stream

	Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Customer Leak
Flow Rate (L/min)	20
Has the leak been called in by DS Technician?	No
Job Ref	LD024
Leak Visible	No



Comments

Turned meter on & it started spinning over. Walked up very steep long driveway & noticed water running down steep slope near top of driveway.

Walked around to corner footing of house & noticed water pushing through ground at stone footing of building. Near where telstra cable enters building.

Couldn't probe onto service line. Hard ground.

Suspect that leak may be on service outside building or inside behind stone footing.

1200/hr

Turned meter off as requested

Photo







