
# Leak Report



## 8 Bowen Street McCrae Victoria 3938 Australia



### **CREATED**

- ① 07/02/2025, 11:18:42 am
- by Morgan Williams

### **LOCATION**

© -38.352052, 144.936051

#### **PROJECT**

South East Water

	McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Valve
Flow Rate (L/min)	0.7
Has the leak been called in by DS Technician?	No
Job Ref	NA
Leak Visible	Yes
Comments	Leak located on Valve. Unable to get valve cover off, sounds like it could be packing.



**Photo** 



