

Message

From: Marsh, Jason [Jason.Marsh@sew.com.au]
Sent: 6/01/2025 9:47:48 AM
To: Swain, Charles [Charles.Swain@sew.com.au]; Pham, Dat [Dat.Pham@sew.com.au]; Derwent, Ascher [Ascher.Derwent@sew.com.au]; MacGregor, David [David.Macgregor@sew.com.au]
Subject: Update 1299522/001 LOCALITY: MCCRAE High Priority
Attachments: IMG_8486.JPG

Team

Arrived on site and greeted by Mark Door SES Controller [PI]

Mark escorted me to the back of property to inspect the landslide.
 Water is running down the washed away embankment. He explained that the property next door is unoccupied due to similar landslide last year, ongoing dispute with council .
 Mark is meeting with council today.

I visited the property above at 10 View Point Road McCrae, meeting the concerned homeowners Gerry and Bronwyn.
 They also own next door (the property in dispute)
 The residents are also having issues with retaining walls leaning, etc.
 I climbed down the embankment and took a sample (before the rain had started).

I have detection services surveying the area and will take new samples to ALS.

Please note: its proximity to the ongoing issues at 4 Waller PI does not present well.

I have detection serviced surveying the area and will take new samples to ALS.

Please check new photos on montage 1299522/001.

Meeting Charles on site tomorrow

Jason Marsh
 Leak Detection Technician



WatersEdge 101 Wells Street
 Frankston VIC 3199

M [PI]



South East Water proudly acknowledges the Traditional Owners of the land on which we work and live, and pay respect to their Elders past, present and emerging. We acknowledge their songlines, cultural lore and continuing connection to the land and water. We recognise and value the rich cultural heritage and ongoing contributions of Aboriginal people and communities to our society in Victoria.

