Task Number: 1323927/001

Task Address: 4 NAVIGATOR STREET, MCCRAE VIC 3938 MapRef:

159A11

**Program Name:** 

Task Work Type: Planned Maintenance - Repair

Source Of Work:

Facility:

Permit Not Required:No Permit Pre Approved:No Permit Reason:Other Permit Other Reason:

Task Story: PI [26/2/2025 20:08] [ALLOCATED] checked [FT] [DNf00100] [27/2/2025 10:26] [IN TRANSIT] Intransit from 10.15am [FT] [DNf00100] [27/2/2025 10:57] [ON SITE SERVICE OK] Arrived did Prestart. Spoke to owner and I found the stoptap spraying out water so I changed the bonnet and washers on the meter ass, the washer was also worn and not isolating. There is an internal leak, so I gave the owner a Red Notice.

Caller Details:jeff PI

Request Details:leak from the s/t misting water away from property. access OK, no dogs. please check if s/t is defective and if it isolates water supply fully

Action Taken :Water Network - Stop Tap - Repair of defect

Task CCT:Water Network - Stop Tap - Repair of leak

Failure Details: 1 Water Stop Tap 20mm to 25mm - Defective - Worn Washer

Task Priority:7 5/03/2025 18:27

Is Chargeable:No Is Pending:No Is Cancelled:No

Is Component Type:No

PO Department: Water Maintenance

PO Supervisor: Contractor:Downer

Created By:Dean, Shaylene Department:Downer Water Supervisor:Pain,Brian

Allocatee:

Task Status: CLOSED

## **Asset List**

Asset	Asset Name	Parent	SI Present?
1050173862	1050173862	1	N

Allocatee History

Allocatee Name	Current	Primary	
DNf00100	N	Y	

SI List

SI Name	Rec
Red Notice	No

Task Number: 1323927/001

Task Story: Payment Type: SEW Sales Code: Contractor CostCode:

Contractor SalesCode:

**Material List** 

Part No	Description	Supplier Contractor	Quantity	Units	Unit Price(\$)	Vehicle	Del Date
61113	Bonnet Brass 20 'T' Head Compl	Downer	1.000	each	CIC	DNv0028	-
69073	Washer Meter 20mm	Downer	2.000	each	0.0	DNv0028	-

Material List (continued...)

Part No	Rec Date	MAC Material Included	Total(\$)
61113	-	No	CIC
69073	1-	No	

Total Materials Cost cic

Labour List

Resource ID	Resource Name	Supplier Contractor	Activity Description	Start Date/Time
DNv0028	DNv0028,630YUU Holden Colorado	Downer	ON SITE SERVICE OK	27/02/2025 10:50
DNv0028	DNv0028,630YUU Holden Colorado	Downer	ON SITE	27/02/2025 10:26
DNv0028	DNv0028,630YUU Holden Colorado	Downer	IN TRANSIT	27/02/2025 10:22
DNe0053	Matthews,Peter	Downer	IN TRANSIT	27/02/2025 10:22
DNe0053	Matthews,Peter	Downer	ON SITE	27/02/2025 10:26
DNe0053	Matthews,Peter	Downer	ON SITE SERVICE OK	27/02/2025 10:50

Labour List (continued...)

Resource ID	End Date/Time	Hours	Est. ChargeRate(\$)	Est. CostRate(\$)
DNv0028	27/02/2025 11:01	0.18		
DNv0028	27/02/2025 10:50	0.40		
DNv0028	27/02/2025 10:26	0.07		
DNe0053	27/02/2025 10:26	0.07		15'
	+		The second contract of	

DNe0053	27/02/2025 10:50	0.40	CIC
DNe0053	27/02/2025 11:01	0.18	CIC

Total Charge Rate: CIC

Total Cost Rate

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price (\$)
DN1000	General Contractor Claim	General Claim	Downer	1.000	each	CIC

Contractor Claims List (continued...)

Claims Code	Total(\$)
DN1000	CIC

Contractor Claims List

chan cairma	Deceription	Quantity	Illnite	Unit Price(\$)	Total/¢)
Service Code	Description	Qualitity	Dillita	Utilit Price(3)	I Otal(3)

Total Claims Cost CIC

Chargeable Items

Item Code	Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)
-----------	-------------	------------------------	----------	-------	-----------------	-----------

Total Chargeable Cost:

**Total Services Cost:** 

Task Cost Scheme: UTA

Is Extra Travel Authorised:No

UTA Item: 9123 - Repair of Domestic Service = 25mm dia. (Above Ground)

Labour Cost CIC

Vehicle Cost

Plant Cost CIC

Materials Cost: CIC

Sub-Total CIC

Travel Adjustment: CIC Actual Adjustment

Adjusted Sub Total: CIC

Risk Events Sub-Total Cost CIC Risk Events Sub-Total Cost

Non-UTA Materials Cost CIC

Total Cost CIC

Total Cost

**UOM Value:** 

Total Quantity CIC

AAC / ARC: CIC

MAC / MRC Value CIC

Service Call Cost:

**Quoted Cost:** 

T&M Labour Cost:

T&M Vehicle Cost:

T&M Plant Cost:

T&M Sub-Total:

T&M Travel Adjustment:

T&M Actual Adjustment:

T&M Adjusted Sub Total:

T&M Material Cost:

T&M Total Cost:

SEW Labour Cost: CIC SEW Vehicle Cost

SEW Plant Cost CIC

SEW Materials Cost CIC

SEW Sub-Total:

SEW Total Contractor Claims CIC

MSF Cost: CIC

Total SEW Cost: CIC

Provisional Contractor Claims CIC

**WSI Details** 

Task	WSI	Planned Start	Actual Start	Planned Finish	Actual Finish	Emergency	Prop Count
ld	ld						

## WSI Details (continued...)

Task Id WSI Status

Task Number: 1323927/001

Task Events

Task Event	Event Date Time	Is Key Event	Allocatee	Is Primary	Is Onsite	ls Work	Is Auto
CLOSED	6/03/2025 18:18	Yes	4.	4.	No	No	Yes
CHECKED	28/02/2025 18:18	Yes	l el .	-	No	No	Yes
DATA COMPLETE	28/02/2025 11:36	Yes	Y I	-	No	No	Yes
WORK COMPLETE	27/02/2025 11:01	Yes		L	No	No	Yes
ON SITE SERVICE OK	27/02/2025 10:50	Yes			Yes	Yes	Yes
ON SITE	27/02/2025 10:26	Yes	E .		Yes	Yes	Yes
IN TRANSIT	27/02/2025 10:22	Yes	-	4	No	Yes	Yes
ALLOCATED	26/02/2025 18:29	Yes			No	No	Yes
AWARDED	26/02/2025 18:27	Yes	-	4	No	No	Yes

Types: Leaking from meter to house

Howlssued : Handed to owner

DaysToRepair: 7

FollowUpNotes: Plumber on to it needed top isolate first









