

Contact:

Address:

## **CERTIFICATE OF ANALYSIS**

24-74742 **Batch No:** Page 1 of 2

Final Report 240932

Caribbean Business Park, Address **South East Water Corporation** Client:

22 Dalmore Drive,

Scoresby,

VIC 3179

FRANKSTON Phone 03 8756 8000 VIC Fax 03 9763 1862 3199 Stuart Paarman Contact: **AUSTRALIA** 

Laboratory

Client Manager

@alsglobal.com

Scoresby Laboratory

PO No: SEW104045 24-Dec-2024 - 30-Dec-2024 Date Sampled:

Jason Marsh 30-Dec-2024 Sampler Name: Date Samples Received: 31-Dec-2024 **TPSEWSS** ALS Program Ref: Date Issued:

South East Water - Sewer Spill Investigation Program Description:

**Matthew Maxwell** 

101 Wells Road

Client Ref: 4 Waller PI 1295094-44

The hash (#) below indicates methods not covered by NATA accreditation in the performance of this service .

Method Analysis Method Laboratory Analysis Laboratory Chloride WD045G Scoresby EC WA010 Scoresby

Fluoride WK040LL Scoresby

## Signatories

Name	Title	Name	Title
Asiri Nissanka	Laboratory Technician	Thanh U. Nguyen	Analyst

Samples not collected by ALS and are tested as received.

Calculated results are based on raw data.

Samples are tested within holding time unless otherwise stated.

Page 2 of 2

 Batch No:
 24-74742

 Report Number:
 240932

Client: South East Water Corporation

ALS Program Ref: TPSEWSS

Program Description: South East Water - Sewer Spill Investigation



Sample No	Site Code	Site Description	Sample Type	Sampled Date/Time
10665283	NONE	SEW01 - Storm Water pit	WATER	30/12/24 09:00
10665284	NONE	SEW02 - Road damage	WATER	30/12/24 09:00
10665285	NONE	SEW03 - Road damage	WATER	24/12/24 16:00

Analysis - Analyte	Sample No. Site Code Units	10665283 NONE	10665284 NONE	10665285 NONE
EC - Electrical Conductivity @ 25C	uS/cm	160	640	670
Fluoride - Fluoride, as F	mg/L	0.80	0.27	0.29
Chloride - Chloride, as Cl	mg/L	29	120	120

A blank space indicates no test performed.