


Leak Report



4 Waller Place McCrae Victoria 3938 Australia



CREATED

🕒 24/12/2024, 9:34:19 am
👤 by Simon Gabriel

LOCATION

📍 -38.347991, 144.938091

PROJECT

📁 Service Stream

Leak Address	4 Waller Place McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	No Leaks Found
Has the leak been called in by DS Technician?	Yes
Job Ref	1295094/003
Leak Visible	No

Identified Leaks

a4c184c5-834f-4d6e-8fcb-cde7b68b94a0

Comments

Simon from DS and Jason Marsh (SEW) on-site to investigate

Sounded all assets in the area, followed suspect 300mm main and no leaks were detected. Chlorine sample needs to be taken when rain stops.

The new owners at 4 Waller and the owner Bret of number 5 (has lived here for the past 20 years) has let us at the back of his block where he has an old Water style lid cover (see attached photos) it houses the 14" main elbow it's very deep 4m is actually not on his property, although it's fencing inside his property, we just popped the and sounded it directly, no noise at all. Apparently the drains run all year round, but the water has got a lot worse and it's affected on the roadways and two locations bubbling up and damaging the road. It been partially barricaded of.



We also surveyed Bayview Rd above the Highway with no leak noises detected.

I don't believe there's any leaks on the mains but still some of the smaller pipes really haven't checked out. Jason Marsh will return take samples when it's not raining for a few days.

Photo

Identified Leaks

a4c184c5-834f-4d6e-8fcb-cde7b68b94a0



Identified Leaks

a4c184c5-834f-4d6e-8fcb-cde7b68b94a0



Identified Leaks

a4c184c5-834f-4d6e-8fcb-cde7b68b94a0

