
# Leak Report



# 13 Bentley Road McCrae Victoria 3938 Australia



## **CREATED**

- ② 26/05/2025, 1:02:04 pm
- by Stuart Haggett

## **LOCATION**

◎ -38.363333, 144.919925

#### **PROJECT**

Service Stream

Leak Address	13 Bentley Road McCrae Victoria 3938 Australia
Zone	South East Water ► Reactive Leaks
Leak Asset Type	Customer Leak
Flow Rate (L/min)	0.1
Has the leak been called in by DS Technician?	No
Job Ref	LD00018
Leak Visible	No



#### Comments

Arrived onsite, plumbers already onsite & have replaced sections of service line down the side of house.

They dug around front garden tap thinking there was a weeping leak around garden tap Junction, but ground dry. They will replace garden tap as riser is rusting away.

Turned meter back on & no noise or movement on meter.

Believe issue has already been resolved by replacing sections of service down the sideway

2hrs travel 1hr onsite

#### **Photo**



