PSM5665 - McRaes Weekly Summary Cost to Date Weekly Cost Invoiced to Date Costs to Invoice Cost Code PSM05665.00.000 Project Management PSM05665.00.001 Meetings PSM05665.00.002 Initial response PSM05665.00.010 EO Area - Site investigation and Factual Reporting PSM05665.00.020 Escarpment - Site investigation and Factual reporting I&S PSM05665.00.030 Monitoring Systems PSM05665.00:040 Geotechnical Assessment & Report PSM05665.00.050 Coburn Avenue Geotechnical Investigation & Advice PSM05665.00.060 Temporary Works

I&S

- Weekly Summary of Completed Tasks 1. PSM5665-GFR Rev B issued (28/03/2025)
- MPSC progress meeting
- 3. Critical monitoring for MBS inspection (25/03/2025)
- 4. Issued quotation for additional LiDAR/photogrammetry survey

Tasks Ongoing

- 1. Remote critical monitoring for Site inspection on 1/04/2025
- 2. Escarpment area landslide characterization (Site inspection)
- 3. Monitoring report installation/methodology
- 4. Geotechnical Assessment Evacuation Order Area
- 5. Reporting for pile testing at 6 View Point Road Internal technical review

Requests for Information Summary

1. Refer to RFI Register PSM5665-0320 Rev 7 (copy atatched).

Scope and Budget Summary

1. Reverse brief and proposal issued on 07/02/2025.

RFIID	RFI Email Title	RFI Email Issue Date	RFI Recipient	Requested Documents	Action By	Status	Documents/Information Provided [Yes/No]	Additional Comment
1	RE: Permits for 3 Penny Lane McCrae - Extension	10:02am 7/01/2025	Matt.Glover@mornpen.vic.gov.au	Have you got structural drawings for the Borghesi Retaining Wall?	Matt Glover (MPSC)	Closed	Yes	Received on 1:26pm 7/01/2025
	to Carport and Store Issued 16/07/2012							
2		9:08pm 21/01/2025	lhovendene@ha.legal	the supporting and stamped soil test report - I am particularly curious about the more	MPSC	Closed	Yes	Received on 29/01/2025
	Landslip site [IMAN-ACTIVE.FID870964]		bbroadhead@ha.legal	modern builds, old ones not so much. That is				
				•B View Point,				
				•10-12 View Point we have there alteration plans already				
				•16 View Point (was built post AGS 2007)				
				•Ill View Point				
				•116 Prospect Hill Road				
				•599 Point Nepean Road.				
				Can Council please provide the drawings and Geotech on file. Particularly interested in 5				
				Prospect as the owner reported ground water in his intrusive investigation.				
3	RE: PSM5665 Impacted / at danger properties -	9:08pm 21/01/2025	lhovendene@ha.legal	For Council - records from Fulton Hogan for construction of stormwater useful on View	MPSC	Closed	Yes	Water Chemistry Testing received on 4:22pm
	Landslip site [IMAN-ACTIVE.FID870964]		bbroadhead@ha.legal	Point. Repairs and testing to Charlesworth Street (this year). Water chemistry testing that				29/01/2025
				Enviro team completed on behalf of Building Inspector team. Camera inspections of stormwater on View Point.				Stormwater and Water sampling in Brief documents received on 7/02/2025
	RE: PSM5665 Impacted / at danger properties -	9:08pm 21/01/2025	lhovendene@ha.legal	For SEW - I believe they have pressure tested, camera inspection etc of assets on View	SEW	closed	N-	SEW will not provide
4	Landslip site [IMAN-ACTIVE.FID870964]	9.08pm 21/01/2025	bbroadhead@ha.legal	Point. Water chemistry testing if available.	SEW	ctosed	NO	SEW WILL HOLD FOUNDE
5	RE:PSM5665 DOCUMENTS REQUIRED-	12:50pm 22/01/2025	lhovendene@ha.legal	Point, water chemistry testing if available. Regarding the 2023 brief – we only need Document 12 (Civil test most latest landslip report	Hanwood Androws	Open	No	PSM has on file, but should be included in new
5	Impacted / at danger properties - Subject to	12.50pm 22/01/2025	inovendene@na.iegal bbroadhead@ha.legal	which includes facts like borehole log reports and labs).	i, maiwoou Anurews	Open	140	brief.
	Legal Professional Privilege [IMAN-		pproauteau@na.tegat	winer includes racts like dorenote tog reports and tabs).	1			Dilei.
	Legal Professional Privilege (IMAN- ACTIVE.FID1000052)		1		1			
6	RE:PSM5665 DOCUMENTS REQUIRED-	12:50pm 22/01/2025	lhovendene@ha legal		MPSC	Closed	Yes	Refer to more recent RFI regarding archived data
0	Impacted / at danger properties - Subject to	22.30pm 22/01/2025	bbroadhead@ha.legal	Suggest we just ask for all planning docs from Council in the EO – reasoning it will pick up		Siosed		The state of the factor of the state of the
	Legal Professional Privilege [IMAN-	I	SS. Sadifead@fia.tegat	atterations (e.g. Borghesi renovation which has the survey file/site drainage in it at that	1			
	ACTIVE.FID1000052]		1	time). I believe the planning team will be putting this together anyway.	1			
7	PSM5665 paper of reference - susceptibility	5:51pm 22/01/2025	lhovendene@ha.legal	We would like the supporting GIS files that this paper claims to have developed. The screen	MPSC	Closed	Yes	Received on 5:26pm 24/01/2025
,	or loose paper or reference susceptibility	0.01pm 225 0172020	bbroadhead@ha.legal	shot you shared regarding the escarpment yesterday appears to be based on this work.	1	Closed	165	necessed on otzopin 24/01/2020
			bb/ oddinedd@nd.tegat	shot you shared regarding the assurptions yesterady appears to be based on this work.				
8	RE: PSM5665 Weekly update week ending 31/01/	8:07am 31/01/2025	Emily.Harkin@mornpen.vic.gov.au	Council records for 2010 LiDAR completed for hydrological study (MBS Dave mentioned	MPSC	Closed	No	Alternate Lidar files supplied
Ü	,		lhovendene@ha.legal	this was done).	1			
			bbroadhead@ha.legal					
9	RE: PSM5665 Weekly update week ending 31/01/	8:07am 31/01/2025	Emily.Harkin@mornpen.vic.gov.au	Preferred supplier of vacuum excavation trucks – does the FH alliance have this equipment	MPSC	Closed	Yes	Council (Tony and Luke MPSC) will organise
-			lhovendene@ha.legal	and can PSM use it? Can Council coordinate this?				
			bbroadhead@ha.legal					
10	RE: PSM5665 Weekly update week ending 31/01/	8:07am 31/01/2025	Emily.Harkin@mornpen.vic.gov.au	SEW records of repairs to Sewer trench to 6 View Point Road. Property owner records of	SEW	closed	No	
			lhovendene@ha.legal	trench at time of repairs.				
			bbroadhead@ha.legal					
11	RE: PSM5665 Weekly update week ending 31/01/	8:07am 31/01/2025	Emily.Harkin@mornpen.vic.gov.au	Photographs and videos of 10 and 6 View Point Road of landslide area prior to and during	MPSC	Open	No	
			lhovendene@ha.legal	the event. It is my understanding that 6 View Point has a drone video from 2023.				
			bbroadhead@ha.legal					
12	RE: PSM5665 Urgent RFI - 6 View Point Road	10:47am 31/01/2025	Emily.Harkin@mornpen.vic.gov.au	6 View Point Drive – plumbing drawings. It is our understanding that there are buried tanks	MPSC	Closed	Yes	Received on 2:21pm 1/02/2025
			lhovendene@ha.legal	immediately adjacent to the bayside exit of the laundry. The outlet is unknown – drawings				
			bbroadhead@ha.legal	suggest re-use as grey water on site. This area is immediately behind the head scarp of the	:			
				landslide.				
13	PSM5665 RFI - Historical surveys	3:47pm 3/02/2025	Emily.Harkin@mornpen.vic.gov.au	To feed into assessments of hillside hazards and to assess cut/fill works on the escarpmen	t MPSC	closed	yes	Received on 5:43pm 5/02/2025
		I	lhovendene@ha.legal	can Council please check what archived survey files they have available?	1			
			bbroadhead@ha.legal		1			
			1	We are particularly interested in any 1 m to 10 m contours from the 1980s, 1990s, early	1			
			1	OOs. These may be old hard copy drawings.	1			
		I	1		1			
			1	The MBS team (Dave) mentioned that there may also be a 2010 LiDAR file available.	1			
			1		1			
		L	<u> </u>	We would be interested in the broad escarpment area as previously defined.	L			
14	PSM5665 6 View Point greywater access	9:09am 5/02/2025	Emily.Harkin@mornpen.vic.gov.au	During service clearance works yesterday the locator identified what appears to be a	MPSC	closed	yes	Phone call with Dayle of 6 View Point on
			lhovendene@ha.legal	charged grey water outlet on 6 View Point Road (i.e. as it was unscrewed it started to leak	1			6/02/2025. require drawings from them.
		I	bbroadhead@ha.legal	water).	1			
			1	0-4-4	1			
			1	Can the team please confirm with the property owner what this feature is and if it has	1			
		I	1	connectivity to the tanks. If the owners could check their plumbing drawings that would also be helpful.	1			
45	RE: Meeting 030225 - Crisis Management	11:34am 5/02/2025	Emily.Harkin@mornpen.vic.gov.au	also be helpful. Can we please request additional information from SEW on the following addresses:	SEW	closed	N-	SEW not providing information
15	Working Group - SEW report Jan Road Opening	11.348111 5/02/2025	Emity.Harkin@mornpen.vic.gov.au lhovendene@ha.legal			ciosed	140	SEW not providing information
	Working Group - SEW report Jan Road Opening Permits-Subject to LPP [IMAN-	I	lhovendene@ha.legal bbroadhead@ha.legal	•3 Charlesworth (1304490/004). It is my understanding from conversations with SEW reps	1			
		I	pproagneag@na.tegat	on site that they did chemistry testing on the water. This is also on their website.				
	ACTIVE.FID1000052]		1	•3 Penny Lane (1299529/004) – again I believe they sampled the landslide water (SEW reps	5			
		I	1	mentioned high chlorides (well above and outside possible potable range)).	1			
		I	1	Then once that is supplied it goes to Risk and Causation and Charlesworth.	1			
		I	1	men once that is supplied regues to rusk and Causadon and Charlesworth.	I			
			1	Historical surveys requested will do to risk /e.d. credible course accordated with out/fill)	1			
			1		1			
				Historical surveys requested will go to risk (e.g. credible source associated with cut/fill), escarpment brief and cause.				

RFIID	RFI Email Title	RFI Email Issue Date	RFI Recipient	Requested Documents	Action By	Status	Documents/Information Provided [Yes/No]	Additional Comment	
16	FW: Water Sampling Results 9/1/2025 locations-	1:18pm 5/02/2025	Emily.Harkin@mornpen.vic.gov.au	I still can't place the results for the 3 Penny Lane testing (shared image attached).	MPSC	Closed	Yes	Received on 2:04pm 5/02/2025	
			Rory.MacDonald@mornpen.vic.gov.au						
				Lab results run from Sample 202 onwards (Shared image (1) attached.					
				Can you please follow up?					
				Can you please tollow up:					
				It may be that the numbers on the bottles were superseded by those in the Chain of					
				Custody. Can the team please confirm.					
17	RE: 565 Point Nepean Rd-Subject to Legal Profess	6:55pm 5/02/2025	Emily.Harkin@mornpen.vic.gov.au	Suggest as a matter of urgency council notify the property owner that we would like to	MPSC	closed	Yes	MBS/PSM inspected 10/02/2025. Matter is with	
			tom.haines-	inspect the property [565 Point Nepean Rd]				MBS.	
			sutherland@mornpen.vic.gov.au						
				This area has a history of landslides (1952).					
18	PSM5665 565 Point Nepean Rd-Subject to Legal I	9:35am 6/02/2025	Emily.Harkin@mornpen.vic.gov.au	Council GIS files of stormwater network (will need this for escarpment area anyway – up to	MPSC	closed	yes	4/03/2025	
			tom.haines- sutherland@mornpen.vic.gov.au	and including Bay View/Outlook Road area)					
19	PSM5665 565 Point Nepean Rd-Subject to Legal I	9:35am 6/02/2025	Emily.Harkin@mornpen.vic.gov.au	Internal Sewerage plans (this is the SEW property connect portal I discussed yesterday) for	MPSC	Closed	ves	Tom (MPSC) - "PSM to source these"	
19	To nooco oco i omercepean na oabject to regard	0.000111 0.0272020	tom.haines-	both 565 Point Nepean Road and 1 to 10 The Eyrie.	100	Olobed	jes	PSM downloaded 1 to 10 The Eyrie on 6/02/2025	
			sutherland@mornpen.vic.gov.au	, , , , , , , , , , , , , , , , , , , ,					
20	PSM5665 565 Point Nepean Rd-Subject to Legal I	9:35am 6/02/2025	Emily.Harkin@mornpen.vic.gov.au	Approved planning docs for 565 point nepean including attached geotech and survey.	MPSC	closed	yes	9/02/2025	
			tom.haines-						
			sutherland@mornpen.vic.gov.au						
21	PSM5665 565 Point Nepean Rd-Subject to Legal I	9:35am 6/02/2025	Emily.Harkin@mornpen.vic.gov.au	Historical/archived MPSC documents for all properties (as per 3 penny lane, this has very	MPSC	Closed	Yes	EO Area only	
			tom.haines-	useful history of past call outs/old septic lines/renovations/levels/survey etc)					
22	PSM5665 565 Point Nepean Rd-Subject to Legal I	0.05 0.00.0005	sutherland@mornpen.vic.gov.au Emily.Harkin@mornpen.vic.gov.au	Access to 553 to 567 Point Nepean Road, 1 to 10 Eyrie (the old gully features here crosses	MDCC	0	No.	PSM to provide a formal list of properties when needed (pau	
22	PSM3003 303 POINT Nepean Ru-Subject to Legal I	9:354111 6/02/2025	tom.haines-	several properties).	MPSC	Open	NO	PSM to provide a format list of properties when needed (pad	iseu as 01 4/03/20.
			sutherland@mornpen.vic.gov.au	several properties).					
23	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal	1.MVater demand upstream and downstream of the Bayview Road/Outlook Road 150 mm	SEW	Closed	No	SEW not providing information	
20			bbroadhead@ha.legal	PVC main over the past 3 years (and up to 5 years if they are willing to share).					
24	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal	2. Any water chemistry testing (field and independent laboratory (understood to be ALS))	SEW	Closed	No	SEW not providing information	
			bbroadhead@ha.legal	associated with the statement on the SEW Website. Waller Place, Charlesworth, Penny					
				Lane, View Point Road/Prospect Hill Road. PSM is aware through conversations in the field					
				with SEW staff of where their technicians sampled and that this includes at a minimum					
	PSM5665 SEW RFI	11:32am 6/02/2025		Charlesworth/Waller Place and Penny Lane.	OF W			OFIN A STATE OF A STAT	
25	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal bbroadhead@ha.legal	Reporting on repairs made to sewer trench connection to 6 View Point Road in December 2022. Property owner logged the request with SEW.	SEW	Closed	No	SEW not providing information	
26	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal	2022. Property owner togged the request with 3EW.	SEW	Closed	No	SEW not providing information	
20			bbroadhead@ha.legal	4.Reporting on fat blockages in View Point Road sewer.	I				
27	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal		SEW	Closed	No	SEW not providing information	
			bbroadhead@ha.legal	5.ECTV on Sewers in View Point Road, Prospect Hill Road, Charlesworth/Waller Ln and					
				Across to Outlook/Bayview.					
28	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal		SEW	Closed	No	SEW not providing information	
			bbroadhead@ha.legal	6.Repair reporting for Outlook Bayview water main break.					
29	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal bbroadhead@ha.legal	7. All pressure testing/leak detection facts from View Point Road/Prospect Hill Road.	SEW	Closed	No	SEW not providing information	
30	PSM5665 SEW RFI	11:32am 6/02/2025	lhovendene@ha.legal	7.Mit pressure testing/teak detection racts from view Fornt Noad/Frospect Hitt Noad.	SEW	Closed	No	SEW not providing information	
50	1 0 1 0 0 0 0 0 E W 1 11 1	11.024111 0/02/2020	bbroadhead@ha.legal	8.All repair reporting for works in Council Road openings including backfill/compaction	J	Olobed		SET 11St providing information	
				details (e.g. Charlesworth test pit excavated on 24/01/2025). Photographic evidence					
				attached.					
31	PSM5665 RFI - Council LiDAR	2:53pm 6/02/2025	Emily.Harkin@mornpen.vic.gov.au	Can we please request from the GIS team the following tiles from the 2018 LiDAR data set:	MPSC	Closed	Yes	Multiple raw lidar files provided	
			lhovendene@ha.legal	e320n5753, e320n5754 and e319n5754.					
			bbroadhead@ha.legal						
32	PSM5665 RFI 599 Point Nepean Road	1:12pm 14/02/2025	Leesa Hovendene, Emily Harkin	EO for 599 Point Nepean Road during construciton in 2021.	MPSC	closed	yes	14/03/2025 data pack	
33	PSM5665 SEW RFI	9:20am 19/02/2025	Emily Harkin, Leesa Hovendene, Ben	Frequency of water main failures. Total length of water main in McCrae and Dromana	SEW	Closed	no	SEW not providing information	
	POMEOGR DEL S D	0.40014.00/00/00/	Broadhead		Mana				
34	PSM5665 RFI - 5 Prospect Hill Road	3:10PM 20/02/2025	lhovendene@ha.legal	Original geotechnical report	MPSC	closed	NO .	original not on file	
35	PSM5665 Building permit drawings - RFI 6 View Po	10:17am 20/02/2025	Emily Harkin Emily Harkin, Leesa Hovendene, David	Building permit drawings and calculations, Building inspector photos/notes	MPSC	closed	ves	David has finished enquiries. Records destroyed.	
35	r 3m3000 building permit drawings - KFT6 View Pi	10.17811120/02/2025	Kotsiakos	building permit drawings and calculations, building inspector photos/notes	PIFOU	ciosed	yes	David has milistred enquiries. Records destroyed.	
36	PSM5665 RFIs and owner consent	9:53am on 11/03/2025	Emily Harkin, Leesa Hovendene, David	Building permit geotech for 15 The Eyrie, 599 Point Nepean Road, 10-12 View Point Road	MPSC	Open	Partial	Awaiting permission 10-12 VP Road	
36			Kotsiakos, Derek Rotter	permissions	I	Spc		The state of the s	
							u.		
37	PSM5665 Stormwater video on Prospect Hill Road	1:20pm on 25/02/2025	Derek Rotter, Emily Harkin, Leesa	CCTV on Sewers in prospect hill road (Length C to D) following an unclear CCTV taken earli	e MPSC	Open	NO	Awaiting response	