



## Weekly Summary of Completed Tasks

- NDT02 in Sewer trench in front of 6 View Point Road. Red dye tracing started on 3/03/2025
- 2. EO area intrusive investigation complete with minor groundwater monitoring and dye tracing to be completed
- 3. PSMS665-050M monitoring letter issued and supporting emails/discussion with MPSC
- 4. Prism survey, Thursday 6/03/2025
- 5. Intrusive test location survey, Friday 7/03/2025 6. Pile testing 6 View Point Drive, 7/03/2025 7. Install two additional GPS sensors , 7/03/2025

- 8. MPSC progress meeting
- 9. Critical monitoring for pile testing at 6 View Point Road
- 10. Property owner meeting regarding SEW water main, 7/03/2025

## Tasks Ongoing

- 1. Factual reporting EO Area
- 2. Weekly survey of prisms
- 3. Monitoring report (second issue)
- 4. Reverse brief for stormwater and sewer investigation Outlook Drive to Point Nepean Road
- 5. Escarpment area landslide characterization (LIDAR and aerial photos).

## Requests for Information Summary

1. Refer to RFI Register PSM5665-0320 Rev 4 (copy atatched).

## Scope and Budget Summary

1. Reverse brief and proposal issued on 07/02/2025.

| RFIID | RFI Email Title   | RFI Email Issue Date |   | Requested Documents   | Action By          | Status | Documents/Information Provided [Yes/No] | Additional Comment  |
|-------|---|----------------------|---|---|--------------------|--------|---|---|
| 1     | RE: Permits for 3 Penny Lane McCrae -   | 10:02am 7/01/2025    | Matt.Glover@mornpen.vic.gov.au  | Have you got structural drawings for the Borghesi Retaining Wall?   | Matt Glover (MPSC) | Closed | Yes                                     | Received on 1:26pm 7/01/2025  |
|       | Extension to Carport and Store Issued<br>16/07/2012   |                      |   |   |                    |        |   |   |
| 2     |   | 9:08pm 21/01/2025    | lhovendene@ha.legal<br>bbroadhead@ha.legal                                    | the supporting and stamped soil test report - I am particularly curious about the more modern builds, old ones not so much. That is   - 8 View Point 8 View Point we have there alteration plans already  - 16 View Point (was built post AGS 2007)  - 4 View Point (was built post AGS 2007)  - 4 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 8 View Point (was built post AGS 2007)  - 10 View Point (was built post AGS 2007)  - | MPSC               | Closed | Yes                                     | Received on 29/01/2025  |
| 3     | RE: PSM5665 Impacted / at danger properties -   | 9:08pm 21/01/2025    | lhovendene@ha.legal   | Can Council please provide the drawings and Geotech on file. Particularly interested in 5<br>Prospect as the owner reported ground water in his intrusive investigation.  For Council - records from Fulton Hogan for construction of stormwater useful on View.  | MPSC               | Closed | Yes                                     | Water Chemistry Testing received on 4:22pm  |
|       | Landslip site [IMAN-ACTIVE.FID870964]   |                      | bbroadhead@ha.legal   | Point. Repairs and testing to Charlesworth Street (this year). Water chemistry testing that<br>Enviro team completed on behalf of Building Inspector team. Camera inspections of<br>stormwater on View Point.   |                    | Closed | 163                                     | 29/01/2025<br>Stormwater and Water sampling in Brief<br>documents received on 7/02/2025 |
| 4     | Landslip site [IMAN-ACTIVE.FID870964]   | 9:08pm 21/01/2025    | lhovendene@ha.legal<br>bbroadhead@ha.legal                                    | For SEW - I believe they have pressure tested, camera inspection etc of assets on View<br>Point. Water chemistry testing if available.  | SEW                | closed | No                                      | SEW will not provide  |
| 5     | RE:PSM5665 DOCUMENTS REQUIRED-<br>Impacted / at danger properties - Subject to<br>Legal Professional Privilege [IMAN-<br>ACTIVE.FID1000052] | 12:50pm 22/01/2025   | lhovendene@ha.legal<br>bbroadhead@ha.legal                                    | Regarding the 2023 brief – we only need Document 12 (Civil test most latest landslip report, which includes facts like borehole log reports and labs).  | Harwood Andrews    | Open   | No                                      | PSM has on file, but should be included in new brief.                                   |
| 6     | RE:PSM5665 DOCUMENTS REQUIRED-<br>Impacted / at danger properties - Subject to<br>Legal Professional Privilege [IMAN-<br>ACTIVE.FID1000052] | 12:50pm 22/01/2025   | bbroadhead@ha.legal   | Suggest we just ask for all planning docs from Council in the EO – reasoning it will pick up alterations (e.g. Borghesi renovation which has the survey file/site drainage in it at that time). I believe the planning team will be putting this together anyway.   | MPSC               | Closed | Yes                                     | Refer to more recent RFI regarding archived da  |
| 7     | PSM5665 paper of reference - susceptibility   | 5:51pm 22/01/2025    | lhovendene@ha.legal<br>bbroadhead@ha.legal                                    | We would like the supporting GIS files that this paper claims to have developed. The<br>screen shot you shared regarding the escarpment yesterday appears to be based on this<br>work.  | MPSC               | Closed | Yes                                     | Received on 5:26pm 24/01/2025   |
| 8     | RE: PSM5665 Weekly update week ending 31/01.  | 8:07am 31/01/2025    | Emily.Harkin@mornpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | Council records for 2010 LIDAR completed for hydrological study (MBS Dave mentioned this was done).   | MPSC               | Closed | No                                      | Alternate Lidar files supplied  |
| 9     | RE: PSM5665 Weekly update week ending 31/01   | 8:07am 31/01/2025    | Emity.Harkin@mornpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | Preferred supplier of vacuum excavation trucks – does the FH alliance have this equipment and can PSM use it? Can Council coordinate this?  | MPSC               | Closed | Yes                                     | Council (Tony and Luke MPSC) will organise  |
| 10    | RE: PSM5665 Weekly update week ending 31/01.  |                      | Emily.Harkin@mornpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | SEW records of repairs to Sewer trench to 6 View Point Road. Property owner records of trench at time of repairs.   | SEW                | closed | No                                      |   |
| 11    | RE: PSM5665 Weekly update week ending 31/01.  |                      | Emily.Harkin@mornpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | Photographs and videos of 10 and 6 View Point Road of landslide area prior to and during the event. It is my understanding that 6 View Point has a drone video from 2023.   | MPSC               | Open   | No                                      |   |
| 12    | -   | 10:47am 31/01/2025   | Emily.Harkin@mornpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | 6 View Point Drive – plumbing drawings. It is our understanding that there are buried tank:<br>immediately adjacent to the bayside exit of the laundry. The outlet is unknown – drawings<br>suggest re-use as grey water on site. This area is immediately behind the head scarp of<br>the landside.  |                    | Closed | Yes                                     | Received on 2:21pm 1/02/2025  |
| 13    | PSM5665 RFi - Historical surveys  | 3:47pm 3/02/2025     | Emily-Harkin@mormpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | To feed into assessments of hilliside hazards and to assess cut/fill works on the escarpment can Council please check what archived averye files they have available?  We are particularly interested in any 1 m to 10 m contours from the 1980s, 1990s, early 00s. These may be old hard copy drawings.  The MBS team (Dave) mentioned that there may also be a 2010 LIDAR file available.  We would be interested in the broad escarpment area as previously defined.   | MPSC               | closed | yes                                     | Received on 5:43pm 5/02/2025  |
| 14    | PSM5665 6 View Point greywater access   | 9:09am 5/02/2025     | Emily.Harkin@mornpen.vic.gov.au<br>Ihovendene@ha.legal<br>bbroadhead@ha.legal | During service clearance works yesterday the locator identified what appears to be a charged grey water outlet on 6 View Point Road (i.e. as it was unscrewed it started to leak water).  Can the team please confirm with the property owner what this feature is and if it has connectivity to the tanks. If the owners could check their plumbing drawings that would also be helpful.   | MPSC               | closed | yes                                     | Phone call with Dayle of 6 View Point on<br>6/02/2025. require drawings from them.      |
| 15    | RE: Meeting 030225 - Crisis Management<br>Working Group - SEW report Jan Road Opening<br>Permits-Subject to LPP [MAN-<br>ACTIVE.FID1000052] | 11:34am 5/02/2025    | Emily,Harkin@mornpen.vic.gov.au<br>lhovendene@ha.legal<br>bbroadhead@ha.legal | Can we please request additional information from SEW on the following addresses:  -8 Charlesworth (130440/004). It is my understanding from conversations with SEW reponsite that they did chemistry testing on the water. This is also on their website.  -8 Penny Lane (1299529/004) – again I believe they sampled the landslide water (SEW reps mentioned high chlorides (well above and outside possible potable range)).  Then once that is supplied it goes to Risk and Causation and Charlesworth.  Historical surveys requested will go to risk (e.g. credible source associated with cut/fill), escarpment brief and cause.  | SEW<br>5           | closed | No                                      | SEW not providing information   |

| RFIID | RFI Email Title                                 | RFI Email Issue Date |  | Requested Documents  | Action By | Status | Documents/Information Provided [Yes/No] | Additional Comment                                   |
|-------|---|----------------------|--|--|-----------|--------|---|--|
| 16    | FW: Water Sampling Results 9/1/2025 locations   | 1:18pm 5/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | I still can't place the results for the 3 Penny Lane testing (shared image attached).  | MPSC      | Closed | Yes                                     | Received on 2:04pm 5/02/2025                         |
|       |   |                      | Rory.MacDonald@mornpen.vic.gov.au                    |  |           |        |   |  |
|       |   |                      |  | Lab results run from Sample 202 onwards (Shared image (1) attached.  |           |        |   |  |
|       |   |                      |  |  |           |        |   |  |
|       |   |                      |  | Can you please follow up?  |           |        |   |  |
|       |   |                      |  |  |           |        |   |  |
|       |   |                      |  | It may be that the numbers on the bottles were superseded by those in the Chain of   |           |        |   |  |
|       |   |                      |  | Custody. Can the team please confirm.  |           |        |   |  |
| 17    | RE: 565 Point Nepean Rd-Subject to Legal Profe  | 6:55nm 5/02/2025     | Emily Harkin@morphen vic dov au                      | Surgices as a matter of urgency council notify the property owner that we would like to  | MPSC      | closed | Vac                                     | MBS/PSM inspected 10/02/2025. Matter is with         |
| 17    | Inc. 303 Form Repeat Tro-Subject to Legat Froie | 30.33pm 3/02/2023    | Emily.Harkin@mornpen.vic.gov.au<br>tom.haines-       | Suggest as a matter of urgency council notify the property owner that we would like to<br>inspect the property [565 Point Nepean Rd]   | ini oo    | ctoseu | 163                                     | MBS.   |
|       |   |                      | sutherland@mornpen.vic.gov.au                        | anapoet the property [500 f one respective]  |           |        |   | Thus.  |
|       |   |                      | Satisfiana@mornpan.vio.gov.aa                        | This area has a history of landslides (1952).  |           |        |   |  |
| 18    | PSM5665 565 Point Nepean Rd-Subject to Legal    | 9:35am 6/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | Council GIS files of stormwater network (will need this for escarpment area anyway - up  | MPSC      | closed | yes                                     | 4/03/2025  |
|       |   |                      | tom.haines-  | to and including Bay View/Outlook Road area)   |           |        |   |  |
|       |   |                      | sutherland@mornpen.vic.gov.au                        |  |           |        |   |  |
| 19    | PSM5665 565 Point Nepean Rd-Subject to Legal    | 9:35am 6/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | Internal Sewerage plans (this is the SEW property connect portal I discussed yesterday)  | MPSC      | Closed | yes                                     | Tom (MPSC) - "PSM to source these"                   |
|       |   |                      | tom.haines-  | for both 565 Point Nepean Road and 1 to 10 The Eyrie.  |           |        |   | PSM downloaded 1 to 10 The Eyrie on 6/02/2025        |
|       |   |                      | sutherland@mornpen.vic.gov.au                        |  |           |        |   |  |
| 20    | PSM5665 565 Point Nepean Rd-Subject to Legal    | 9:35am 6/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | Approved planning docs for 565 point nepean including attached geotech and survey.   | MPSC      | closed | yes                                     | 9/02/2025  |
|       |   |                      | tom.haines-  |  | ĺ         |        |   |  |
|       |   |                      | sutherland@mornpen.vic.gov.au                        |  |           |        |   |  |
| 21    | PSM5665 565 Point Nepean Rd-Subject to Legal    | 9:35am 6/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | Historical/archived MPSC documents for all properties (as per 3 penny lane, this has very  | MPSC      | Closed | Yes                                     | EO Area only   |
|       |   |                      | tom.haines-  | useful history of past call outs/old septic lines/renovations/levels/survey etc)   | ĺ         |        |   |  |
|       | DOMESON FOR Delet Newson Del Code               | 0.05 0/00/0005       | sutherland@mornpen.vic.gov.au                        | Annual of Front Ford Point Name of David Att 40 Finis Att and Annual Control   | MDCO      | 0      | Na                                      | DCM to provide a formal list of account.             |
| 22    | PSM5665 565 Point Nepean Rd-Subject to Legal    | 9:35am 6/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | Access to 553 to 567 Point Nepean Road, 1 to 10 Eyrie (the old gully features here crosses   | MPSC      | Open   | NO                                      | PSM to provide a formal list of properties when need |
|       |   |                      | tom.haines-  | several properties).   | ĺ         |        |   |  |
| 23    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | sutherland@mornpen.vic.gov.au<br>lhovendene@ha.legal | 1.Mater demand upstream and downstream of the Bayview Road/Outlook Road 150 mm   | SFW       | Closed | No                                      | SEW not providing information                        |
| 23    | F3H3003 3EW NFI                                 | 11.32411 0/02/2023   | bbroadhead@ha.legal                                  | PVC main over the past 3 years (and up to 5 years if they are willing to share).   | SEVV      | Closed | NO                                      | SEW not providing information                        |
|       |   |                      | bbioadilead@ila.tegat                                | rvc main over the past 3 years (and up to 5 years in they are withing to share).   |           |        |   |  |
| 24    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha.legal                                  | 2. Any water chemistry testing (field and independent laboratory (understood to be ALS))   | SFW       | Closed | No                                      | SEW not providing information                        |
| 24    | TOTIOGG GETVINI                                 | 11.02011 0/02/2020   | bbroadhead@ha.legal                                  | associated with the statement on the SEW Website. Waller Place, Charlesworth, Penny  | oen       | Otobea |   | DEW not providing morniation                         |
|       |   |                      |  | Lane, View Point Road/Prospect Hill Road. PSM is aware through conversations in the  |           |        |   |  |
|       |   |                      |  | field with SEW staff of where their technicians sampled and that this includes at a  |           |        |   |  |
|       |   |                      |  | minimum Charlesworth/Waller Place and Penny Lane.  |           |        |   |  |
|       |   |                      |  | ·  |           |        |   |  |
| 25    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha.legal                                  | 3. Reporting on repairs made to sewer trench connection to 6 View Point Road in  | SEW       | Closed | No                                      | SEW not providing information                        |
|       |   |                      | bbroadhead@ha.legal                                  | December 2022. Property owner logged the request with SEW.   |           |        |   |  |
| 26    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha.legal                                  |  | SEW       | Closed | No                                      | SEW not providing information                        |
|       |   |                      | bbroadhead@ha.legal                                  | 4.Reporting on fat blockages in View Point Road sewer.   |           |        |   |  |
| 27    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha.legal                                  |  | SEW       | Closed | No                                      | SEW not providing information                        |
|       |   |                      | bbroadhead@ha.legal                                  | 5.ICCTV on Sewers in View Point Road, Prospect Hill Road, Charlesworth/Waller Ln and   | İ         |        |   |  |
|       |   |                      | <u> </u>   | Across to Outlook/Bayview.   |           |        |   |  |
| 28    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha.legal                                  |  | SEW       | Closed | No                                      | SEW not providing information                        |
|       | DOMESOE CENTRE!                                 | 44-00 0/00/0005      | bbroadhead@ha.legal                                  | 6.Repair reporting for Outlook Bayview water main break.   | CEM       | 01     | N-                                      | CDM  |
| 29    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha.legal                                  | 7 All procesure testing/leak detection facts from View Point Pood (Pr+ 13) Po  | SEW       | Closed | INU                                     | SEW not providing information                        |
|       |   |                      | bbroadhead@ha.legal                                  | 7.All pressure testing/leak detection facts from View Point Road/Prospect Hill Road.   | ĺ         |        |   |  |
| 30    | PSM5665 SEW RFI                                 | 11:32am 6/02/2025    | lhovendene@ha legal                                  |  | SEW       | Closed | No                                      | SEW not providing information                        |
| 30    | I SHOUS SEW REI                                 | 11.024111 0/02/2025  | lhovendene@ha.legal<br>bbroadhead@ha.legal           | 8.All repair reporting for works in Council Road openings including backfill/compaction  | JL11      | Ciosed | 140                                     | SEAN HOT BLOWING HILDHINGHOLD                        |
|       |   |                      | ры овиневишналеван                                   | details (e.g. Charlesworth test pit excavated on 24/01/2025). Photographic evidence  | ĺ         |        |   |  |
|       |   |                      |  | attached.  | ĺ         |        |   |  |
| 31    | PSM5665 RFI - Council LiDAR                     | 2:53pm 6/02/2025     | Emily.Harkin@mornpen.vic.gov.au                      | Can we please request from the GIS team the following tiles from the 2018 LiDAR data   | MPSC      | Closed | Yes                                     | Multiple raw lidar files provided                    |
| 01    |   |                      | lhovendene@ha.legal                                  | set: e320n5753, e320n5754 and e319n5754.   | I         | Closed |   | pro row was mes provided                             |
|       |   |                      | bbroadhead@ha.legal                                  | 555. 552515755; 552515754 BIN 652515754.   | ĺ         |        |   |  |
| 32    | PSM5665 RFI 599 Point Nepean Road               | 1:12pm 14/02/2025    | Leesa Hovendene, Emily Harkin                        | EO for 599 Point Nepean Road during construciton in 2021.  | MPSC      | OPEN   | NO                                      |  |
| 33    | PSM5665 SEW RFI                                 | 9:20am 19/02/2025    | Emily Harkin, Leesa Hovendene, Ben                   | Frequency of water main failures. Total length of water main in McCrae and Dromana   | SEW       | Closed | no                                      | SEW not providing information                        |
| -     |   |                      | Broadhead  | and state of the s | ľ         |        |   | ,  |
| 34    | PSM5665 RFI - 5 Prospect Hill Road              | 3:10PM 20/02/2025    | lhovendene@ha.legal                                  | Original geotechnical report   | MPSC      | closed | No                                      | original not on file                                 |
| -     |   |                      | Emily Harkin   |  | 1         |        |   |  |
| 35    | PSM5665 Building permit drawings - RFI 6 View   | 10:17am 20/02/2025   | Emily Harkin, Leesa Hovendene, David                 | Building permit drawings and calculations, Building inspector photos/notes   | MPSC      | closed | yes                                     | David has finished enquiries. Records destroyed.     |
|       | 1   |                      | Kotsiakos  |  | ĺ         |        |   |  |
| 36    | PSM5665 RFIs and owner consent                  | 9:53am on 11/03/2025 | Emily Harkin, Leesa Hovendene, David                 | Building permit geotech for 15 The Eyrie, 599 Point Nepean Road, 10-12 View Point Road   | MPSC      | Open   | No                                      |  |
|       |   |                      | Kotsiakos, Derek Rotter                              | permissions  | ĺ         |        |   |  |
|       |   |                      |  |  |           |        |   |  |