

Request ID	2535448	Mornington Peninsula Shire	As at: 16-Apr-25 09:42 AM
Type.	Water - Private Stormwater - Legal Point of Discharge		FINALISED

Customer Information

Irrelevant & Sensitive

Customer: 14 Prospect Hill Road Map:159 B10 14 Prospect Hill Road McCrae 36
MCCRAE 3938 (X Coord: -38.3461873)

Home Phone:**Work Phone:****Mobile Phone:** I/S**eMail:****FAX:****Property No:** 42300**Request Information****Centre:** Mornington Peninsula Shire**Received Via:** Snap Send Solve**Input Officer:** Dalmau, Barbara**Received On:** 06-Feb-23 @ 04:20 PM**Priority:** P3 – 5 Days**Provider:** Shire**Issue Type:** Standard Request**Responsible:** INFD Development Engineering [TB], Team**Reference No:** 3033668**Additional Names****Additional Address**

Primary: 7 Prospect Hill Road McCrae 3938 (Prop. No: 147818) Map 159
B10 12 Prospect Hill Rd, McCrae VIC 3938, Australia

Additional Information**How Received:** SnapSendSolve**Are you reporting a blockage:** No**Request Details:**

SnapSendSolve IncidentType: WaterPollution - Non Sewer related

No 7 Prospect Hill road is diverting water from the property into the street gutter drain system & since this increase theres more water appearing at the end of View Point road around the corner which appears to be connected to the same system. The nature strip outside no 7 Prospect Hill Rd is absolutely saturated & often omits a foul stench. Could this have caused or contributed to the avalanche of the cliff in MCCrae which happened on 15/11/22?

GEOCode: -38.346187591552736 , 144.93638610839844

06-Feb-23 @ 04:20 PM **Request Created**01-Feb-23 @ 05:08 PM **Attachment**

Imported from SnapSendSolve Document:
\\ad.mps\common\webcrm\attachments\2535448_77698_2535

01-Feb-23 @ 05:08 PM **Attachment**

Imported from SnapSendSolve Document:
\\ad.mps\common\webcrm\attachments\2535448_77699_2535

06-Feb-23 @ 04:20 PM **Action ID: 5001973 (Closed)**

Assigned to: INFD Development Engineering [TB] Team
Task given: Accept & Assign This Request for Team
Action was due 07-Feb-23 @ 04:20 PM and was
completed 10-May-23 @ 03:40 PM.

Action taken: Completed - No Further Action Req
Action by: Wood Michelle
06-Feb-23 @ 04:20 PM Notification
Sent to INFD Development Engineering [TB] Team (Action)
Notified note sent by Dalmau Barbara (Automatically)
Message: Email generated for Action: 5001973 for INFD
Development Engineering [TB] Team

16-Feb-23 @ 10:46 AM Notes Comment by Wood Michelle
Sent to D Jones to follow up

17-Feb-23 @ 09:53 AM Reopen Comment by Millen Krystal
Can an investigation please be initiated in to the private storm
water before being sent to roads, draiange and Cleansing
operations.

Request ID	2535448	Mornington Peninsula Shire	As at: 16-Apr-25 09:42 AM
Type.	Water - Private Stormwater - Legal Point of Discharge		FINALISED

06-Feb-23 @ 04:20 PM **Attachment** INFD Development Engineering [TB] Team
SnapSendSolve ReportURL Document:
<https://portal.snapsendsolve.com/reports/3033668/?signature=>

17-Feb-23 @ 09:53 AM **Reopen Comment** Millen Krystal
Can an investigation please be initiated in to the private storm water before being sent to roads, draiange and Cleansing operations.