## Stormwater Drainage Concern

#### Request Summary

2024-092256 Tracking Number: 2024-092256.ISW 09-Nov-2024 19:34:48 Received:

Priority: Urgent Status: Inactive Duplicated From: 2024-081662 Stage: Completed

Address: 18-20 View Point Road MCCRAE VICTORIA 3938

Detail:

18-20 View Point Road MCCKAE VICTORIA 3938

I first reported this blocked side entry pit on the 12th October and it has yet to be cleared? I received a call back message on the 14/10/24 assuring me it would be dealt within 10 business days. We are situated two doors down from the land slip at 10-12 View Point Road and are seeing constant water seepage onto our block 18-20 View Point Road as what we see as the build from spring water not getting away as a consequence of the remedial works undertaken in View Point Road in the last 12 mths. We are fearful that if this blocked pit is not cleared we may suffer a similar land slip event. Your immediate attention to this problem is sought! Could you please respond to me directly as soon as possibl

PΙ

#### Categorisation

Request Type Environment Management

Request Category Flood and Stormwater Management Request Sub Category Stormwater Drainage Concern

# Stage Updates

Date Completed Stage 04-Feb-2025 Completed 27-Nov-2024 Work Scheduled 09-Nov-2024 New Request

### Resolution

Date Resolved Resolution **Resolution Details** 04-Feb-2025 00:00:00 Resolved by Council

2 Pits were vacuumed and 2 lines were jetted on View Point Road McCrae. Works were completed by Shire's contractors on the 26 November 2024.