

Stormwater Drainage Concern

Request Summary

Reference Id:	2024-093705
Tracking Number:	2024-093705.HYW
Received:	13-Nov-2024 19:07:29
Priority:	Urgent
Status:	Inactive
Duplicated From:	2024-081662
Stage:	Completed
Address:	18-20 View Point Road MCCRAE VICTORIA 3938
Detail:	<p>Currently we have a case number 2024-081662 which was first reported on 09/10/24. I spoke to a council representative again today and urged her to follow up as no action has been taken yet. We were assured originally that action would be taken within 14 working days? We are still seeing an increase in surface water on our block which may is having a negative impact on our retaining wall. We fear given the historic land slip at 10-12 View Point Road that the remedial works undertaken in View Point Road above combined with 2 blocked drains are responsible for this water ingress. Please see attached images.</p> <p>We fear that if this issue is not attended to that this water ingress further degrade our retaining wall which is located within 3 metres of our house. Structural failure of this wall could result in significant damage to our home. As requested last week we urge you to undertake an immediate investigation of this matter.</p> <p>Personal Information</p>

Categorisation

Request Type	Environment Management
Request Category	Flood and Stormwater Management
Request Sub Category	Stormwater Drainage Concern

Stage Updates

Date Completed	Stage
04-Feb-2025	Completed
16-Jan-2025	Works Pending
27-Nov-2024	Work Scheduled
15-Nov-2024	Awaiting Inspection
13-Nov-2024	New Request

Resolution

Date Resolved	Resolution	Resolution Details
04-Feb-2025 00:00:00	Resolved by Council	2 Pits were vacuumed and 2 lines were jetted on View Point Road McCrae. Works were completed by Shire's contractors on the 26 November 2024.