Request ID 2505648 **Mornington Peninsula Shire** As at: 20-Jun-25 12:24 PM

Type. Water - Shire Stormwater Drainage Network - Open Drains & Outfalls - Repairs **FINALISED** 

**Customer Information** 

Irrelevant & Sensitive

Customer: 23 Coburn Avenue Map: 159 A10

MCCRAE 3938 (X Coord: -38.347438808333 Y Coord: 144.935736658334)

**Home Phone:** Work Phone:

**Mobile Phone:** 

eMail:

FAX:

Property No: 130676

Linked To: 2505098, 2505165

**Request Information** 

Centre: Mornington Peninsula Shire

Received Via: Telephone

Input Officer: Nicholl, Kester

Received On: 14-Nov-22 @ 07:59 PM

Priority: P3 - 5 Days

Provider: Shire

Issue Type: Standard Request Responsible: SIMS Roads, Team

Reference No:

Additional Names **Additional Address** 

Primary: 23 Coburn Avenue MCCRAE 3938 ( Prop. No: 130676, X Coord:

-38.347438808333Y Coord: 144.935736658334) Map 159 A10

**Additional Information** 

How Received: Telephone

\*\*\*\*\*\*\*\*\*\*Customer Response Management\*\*\*\*\*\*

Does customer wish to be

contacted:

**Request Details:** 

Caller Details Merit Number: 2505648

Caller Type: Customer / Resident Caller Name Irrelevant & Sensitive Contact Number

**Enquiry Details** 

Enquiry Type: Drains / Pits / Flooding Relating To: Storm Water Drains Incident Address: 23 Coburn AVE

McCrae VIC 3938

Nature Of Call: Drains / Pits / Flooding Storm Water Drains.

Yes

Irrelevant & Sensitive Drainage Pipe That He Was Advised Is Redundant Has Been

Flowing Water Onto His Property That Has Opened A 5ft Sinkhole Under His Garage And Flooded The Next Door Property. Seeking To Have Issue

With Pipe Resolved To Avoid Further Water Damage During Next Downpour.

Call Reference Number: 31684126

14-Nov-22 @ 07:59 PM Request Created

14-Nov-22 @ 07:59 PM Action ID: 4945065 (Closed) Assigned to: SIMS Roads Team

Task given: Accept & Assign This Request for Team Action was due 15-Nov-22 @ 07:59 PM and was

completed 15-Nov-22 @ 04:09 PM.

Action taken: Assigned Action by: Piotrowski Jane

15-Nov-22 @ 04:09 PM Notes Comment by Piotrowski Jane

Assigned to AT to inspect. JPiotrowski

Request ID 2505648

Mornington Peninsula Shire

Type. Water - Shire Stormwater Drainage Network - Open Drains & Outfalls - Repairs

20-Jun-25 12:24 PM **FINALISED** 

15-Nov-22 @

11:20 AM Action ID: 4945440 (Closed)

Assigned to: Trebilco Brandon
Task given: Additional Information
Action was due 01-Dec-22 @ 11:08 AM and was
completed 30-Nov-22 @ 04:17 PM.

As at:

Action taken: Completed
Action by: Trebilco Brandon

15-Nov-22 @ 11:20 AM Notes Comment by Cook Kaylene Customer would like this case to be investigated by a specialist drainage engineer from the Shire.

16-Nov-22 @ 11:40 AM Notes Comment by Trebilco Brandon Inspected and spoke with customer, also have been emailing. large sinkhole has formed possibly threatening house, we are having underground specialists getting out there asap to investigate, from there we will undertake excavation and repaire works.

30-Nov-22 @ 04:17 PM Notes Comment by Trebilco Brandon Cavity around old drianage system filled with treated sand. organising meeting with SEW as cavities/voids still exist around the water main. closing off case as we have done everything on our end, now just need SEW to excavate and investigate around the main/trench.

15-Nov-22 @

11:20 AM Notification

Ν

Message: Manual Action Created

15-Nov-22 @

04:09 PM Action ID: 4946032 (Closed)

Assigned to: Provisional Works SIMS Roads Pending Task given: Investigate & Respond To Customer Action was due 29-Nov-22 @ 04:09 PM and was completed 02-Dec-22 @ 02:44 PM.

Sent to Trebilco Brandon (Action)

Action taken: Completed - No Further Action Req Action by: Twaites Michelle 15-Nov-22 @ 04:09 PM Notification Sent to Provisional Works SIMS Roads Pending (Action) Notified note sent by Piotrowski Jane (Automatically) Message: Email generated for Action: 4946032 for Provisional Works SIMS Roads Pending

02-Dec-22 @ 02:44 PM Notes Comment by Twaites Michelle All works completed as per notes from BT. SEW still have further works and BT will advise AT if anything further is identified for MPSC to repair. MTwaites

02-Dec-22 @

02:46 PM Link Comment

Linked Request 2505648 to 2505165 same issue

Twaites Michelle