

Task Number:1298016/001

Task Address:32 COBURN AVENUE, MCCRAE VIC 3938 MapRef : 159B10

Program Name:

Task Work Type:Planned Maintenance - Repair

Source Of Work:

Facility:

Permit Not Required:No

Permit Pre Approved:No

Permit Reason:Other

Permit Other Reason:

Task Story:[(Personal Information [29/12/2024 16:23] [AWARDED]

Property Number:02E//00435/28 [Scallion,Bradley] [29/12/2024 17:18]

[UNAWARDED] checked, works being done by service stream in mccrae, changing to them as I believe they wil llikely be linked. [Scallion,Bradley]

[29/12/2024 17:20] [AWARDED] 1295094/003 are works being done on waller place, notes state that there is more water in the stream than usual, possibly

due to leak? [FT] [LLf0129] [30/12/2024 08:16] [ON SITE] Arrived on site to

find water pushing up from roadway opposite number 3 Charlesworth St tested

water & reading was high 670 walked up hill sounded services & valves no

noises walked up Waller Place & can hear water gushing in stormwater drain

then [FT] [LLf0129] [30/12/2024 08:25] [ON SITE] [Personal Information

Personal Information | [29/12/2024 16:23] [AWARDED] Property

Number:02E//00435/28 [Scallion,Bradley] [29/12/2024 17:18] [UNAWARDED]

checked, works being done by service stream in mccrae, changing to them as I believe they wil llikely be linked. [Scallion,Bradley] [29/12/2024 17:20]

[AWARDED] 1295094/003 are works being done on waller place, notes state that there is more water in the stream than usual, possibly due to leak?

[Bartholomeusz,Ross] [30/12/2024 08:16] [ON SITE] Arrived on site to find

water pushing up from roadway opposite number 3 Charlesworth St tested

water & reading was high 670 walked up hill sounded services & valves no

noises walked up Waller Place & can hear water gushing in stormwater drain

then SEW Jason Marsh on site we lifted stormwater lid & saw water like a burst

flowing down drain lowered bucket with rope got sample & reading was 160

possible burst up hill on 300mm MSCL near Bayview RD or under freeway &

getting into stormwater drain sounded valve ID 362971 & it was screaming

SEW leak detection & operations are chasing leak will be informed of where

leak is [Shaikh,Anna] [30/12/2024 10:16] [OFF SITE] jane 0417399567 -

reporting water seeping up from outside 32 coburn ave, lifting up the concrete

and creating spongy areas [FT] [SSf0010] [30/12/2024 12:57] [OFF SITE] Leak

has been located on job no-1295094/006

Caller Details:Rob, [Irrelevant & Sensitive

Request Details:water main leakng in the ns, not alot of water

Action Taken :Water Network - Water Main - Inspection

Task CCT:Water Network - Water Main - Repair of leak in nature strip

Failure Details:0 Not Applicable - Not Applicable - Not Applicable

Task Priority:5 30/12/2024 16:23

TaskSummary

Is Chargeable:No
Is Pending:No
Is Cancelled:No
Is Component Type:No
PO Department:Water Maintenance
PO Supervisor:
Contractor:ServiceStream
Created By: Personal Information
Department:ServiceStream Water
Supervisor:Corrin,Jason
Allocatee:
Task Status:CLOSED

Asset List

Asset	Asset Name	Parent	SI Present?
-------	------------	--------	-------------

Allocatee History

Allocatee Name	Current	Primary
SSf0287	N	Y
LLf0129	N	Y
Herrington, Luke	N	Y
SSf0010	N	Y

SI List

SI Name	Rec
---------	-----

Task Number:1298016/001

Task Story:

Payment Type:

SEW Sales Code:

Contractor CostCode:

Contractor SalesCode:

Material List

Part No	Description	Supplier Contractor	Quantity	Units	Unit Price(\$)	Vehicle	Del Date	Rec Date
---------	-------------	---------------------	----------	-------	----------------	---------	----------	----------

Material List (continued...)

Part No	MAC Material Included	Total(\$)
---------	-----------------------	-----------

Total Materials Cost:

Labour List

Resource ID	Resource Name	Supplier Contractor	Activity Description
LLv0240	LLv0240,1NF 3MH Isuzu Service Pack	ServiceStream	IN TRANSIT
SSv0025	SSv0025,1ZY4EP Toyota Hilux	ServiceStream	IN TRANSIT
SSv0025	SSv0025,1ZY4EP Toyota Hilux	ServiceStream	ON SITE
LLe0005	Bartholomeusz,Ross	ServiceStream	IN TRANSIT
LLe0005	Bartholomeusz,Ross	ServiceStream	ON SITE
LLe0726	Johnson,Kelly	ServiceStream	IN TRANSIT

Labour List (continued...)

Resource ID	Start Date/Time	End Date/Time	Hours	Est. ChargeRate (\$)	Est. CostRate (\$)
LLv0240	29/12/2024 18:26	29/12/2024 18:49	0.38	CIC	
SSv0025	30/12/2024 06:48	30/12/2024 06:56	0.13		
SSv0025	30/12/2024 06:56	30/12/2024 08:30	1.57		
LLe0005	30/12/2024 06:48	30/12/2024 06:56	0.13		
LLe0005	30/12/2024 06:56	30/12/2024 08:30	1.57		
LLe0726	29/12/2024 18:26	29/12/2024 18:49	0.38		

Total Charge Rate: CIC

Total Cost Rate:CIC

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price(\$)
SS1000	General Contractor Claim	General Claim	ServiceStream	1.000	each	CIC

Contractor Claims List (continued...)

Claims Code	Total(\$)
SS1000	CIC

Contractor Claims List

Service Code	Description	Quantity	Units	Unit Price(\$)	Total(\$)
--------------	-------------	----------	-------	----------------	-----------

Total Claims Cost: CIC

Chargeable Items

Item Code	Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)
-----------	-------------	---------------------	----------	-------	-----------------	-----------

Total Chargeable Cost:

Total Services Cost:

Task Cost Scheme:Service Call

Is Extra Travel Authorised:No

UTA Item:
Labour Cost:
Vehicle Cost:
Plant Cost:
Materials Cost:
Sub-Total:
Travel Adjustment:
Actual Adjustment:
Adjusted Sub Total:
Risk Events Sub-Total Cost:
Risk Events Sub-Total Cost:
Non-UTA Materials Cost:
Total Cost:
Total Cost:
UOM Value:
Total Quantity:
AAC / ARC:
MAC / MRC Value:
Service Call Cost:
Quoted Cost:
T&M Labour Cost:
T&M Vehicle Cost:
T&M Plant Cost:
T&M Sub-Total:
T&M Travel Adjustment:
T&M Actual Adjustment:
T&M Adjusted Sub Total:
T&M Material Cost:
T&M Total Cost:
SEW Labour Cost:
SEW Vehicle Cost:
SEW Plant Cost:
SEW Materials Cost:
SEW Sub-Total:
SEW Total Contractor Claims
MSF Cost:
Total SEW Cost:
Provisional Contractor Claims

WSI Details

Task Id	WSI Id	Planned Start	Actual Start	Planned Finish	Actual Finish	Emergency	Prop Count
---------	--------	---------------	--------------	----------------	---------------	-----------	------------

WSI Details (continued...)

Task Id	WSI Status
---------	------------

Task Number:1298016/001

Task Events

Task Event	Event Date Time	Is Key Event	Allocatee	Is Primary	Is Onsite	Is Work	Is Auto
CLOSED	6/02/2025 18:19	Yes	-	-	No	No	Yes
CHECKED	31/12/2024 17:33	Yes	-	-	No	No	Yes
DATA COMPLETE	31/12/2024 11:21	Yes	-	-	No	No	Yes
WORK COMPLETE	30/12/2024 12:58	Yes	-	-	No	No	Yes
ON SITE	30/12/2024 06:56	Yes	-	-	Yes	Yes	Yes
IN TRANSIT	29/12/2024 18:26	Yes	-	-	No	Yes	Yes
ALLOCATED	29/12/2024 17:23	Yes	-	-	No	No	Yes
AWARDED	29/12/2024 16:23	Yes	-	-	No	No	Yes









Task Number:1298016/002
Task Address:32 COBURN AVENUE, MCCRAE VIC 3938 MapRef : 159B10
Program Name:
Task Work Type:Planned Maintenance - Repair
Source Of Work:
Facility:
Permit Not Required:No
Permit Pre Approved:No
Permit Reason:Other
Permit Other Reason:
Task Story:[Castle,Ken] [29/12/2024 18:00] [AWARDED] Accidental re-raise of JN 1295094/003 [Castle,Ken] [29/12/2024 18:00] [CANCELLED] Cancelled due to this being a re-raise.
Caller Details:Rob, 0419885017
Request Details:Rob (Ph. 0419885017) confirmed a moderate flowing leak from the roadway above the main. No access issues, no animals.
Action Taken :No Work Cancelled - No Work Cancelled - No Work Cancelled
Task CCT:Water Network - Water Main - Repair of leak in roadway
Failure Details:0 Not Applicable - Not Applicable - Not Applicable
Task Priority:5 30/12/2024 17:49
Is Chargeable:No
Is Pending:No
Is Cancelled:Yes
Is Component Type:No
PO Department:Water Maintenance
PO Supervisor:
Contractor:ServiceStream
Created By:Castle, Ken
Department:ServiceStream Water
Supervisor:Corrin,Jason
Allocatee:
Task Status:CLOSED

Asset List

Asset	Asset Name	Parent	SI Present?
-------	------------	--------	-------------

Allocatee History

Allocatee Name	Current	Primary
----------------	---------	---------

SI List

SI Name	Rec
---------	-----

Task Number:1298016/002

Task Story:

Payment Type:

SEW Sales Code:

Contractor CostCode:

Contractor SalesCode:

Material List

Part No	Description	Supplier Contractor	Quantity	Units	Unit Price(\$)	Vehicle	Del Date	Rec Date
---------	-------------	---------------------	----------	-------	----------------	---------	----------	----------

Material List (continued...)

Part No	MAC Material Included	Total(\$)
---------	-----------------------	-----------

Total Materials Cost:

Labour List

Resource ID	Resource Name	Supplier Contractor	Activity Description	Start Date/Time
-------------	---------------	---------------------	----------------------	-----------------

Labour List (continued...)

Resource ID	End Date/Time	Hours	Est. ChargeRate(\$)	Est. CostRate(\$)
-------------	---------------	-------	---------------------	-------------------

Total Charge Rate:

Total Cost Rate:

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price(\$)	Total (\$)
-------------	-------------	------------	---------------------	----------	-------	----------------	------------

Contractor Claims List

Service Code	Description	Quantity	Units	Unit Price(\$)	Total(\$)
--------------	-------------	----------	-------	----------------	-----------

Total Claims Cost:

Chargeable Items

Item Code	Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)
-----------	-------------	---------------------	----------	-------	-----------------	-----------

Total Chargeable Cost:

Total Services Cost:

Task Cost Scheme:UTA

Is Extra Travel Authorised:No

UTA Item:

Labour Cost

CIC

Vehicle Cost

Plant Cost:

CIC

Materials Cost:

CIC

Sub-Total:

CIC

Travel Adjustment:

Actual Adjustment:

Adjusted Sub Total

CIC

Risk Events Sub-Total Cost

CIC

Risk Events Sub-Total Cost:

Non-UTA Materials Cost:

CIC

Total Cost

CIC

Total Cost

UOM Value:

Total Quantity:

AAC / ARC:

MAC / MRC Value:

Service Call Cost:

Quoted Cost:

T&M Labour Cost:

T&M Vehicle Cost:

T&M Plant Cost:

T&M Sub-Total:

T&M Travel Adjustment:

T&M Actual Adjustment:

T&M Adjusted Sub Total:

T&M Material Cost:

T&M Total Cost:

SEW Labour Cost

CIC

SEW Vehicle Cost

SEW Plant Cost:

CIC

SEW Materials Cost:

CIC

SEW Sub-Total:

SEW Total Contractor Claims

CIC

MSF Cost:

CIC

Total SEW Cost:

CIC

Provisional Contractor Claims

CIC

WSI Details

Task Id	WSI Id	Planned Start	Actual Start	Planned Finish	Actual Finish	Emergency	Prop Count
---------	--------	---------------	--------------	----------------	---------------	-----------	------------

WSI Details (continued...)

--	--	--	--	--	--	--	--

Task Id	WSI Status
---------	------------

Task Number:1298016/002

Task Events

Task Event	Event Date Time	Is Key Event	Allocatee	Is Primary	Is Onsite	Is Work	Is Auto
AWARDED	29/12/2024 17:49	Yes	-	-	No	No	Yes