

















































Task Number:1295094/007

Task Address:4 WALLER PLACE, MCCRAE VIC 3938 MapRef : 159B10

Program Name:

Task Work Type:Unknown - Investigation

Source Of Work:

Facility:

Permit Not Required:No

Permit Pre Approved:No

Permit Reason:Other

Permit Other Reason:

Task Story:[FT] [SSf0010] [2/1/2025 17:56] [ON SITE] Arrived back on site & water is still coming out of the road opp no-3 Charlesworth st & the n/strip at no-1 Waller Pl. I then went to the other side of the freeway to do some leak detection as per Jason Marsh from SEW & found water is seeping out of the middle of the d/way at no-29 Bayview rd & where the d/way meets the road. I tested the water & it did turn pink. There is a 100mm UPVC main that runs along there. I picked up a few faint sounds on nearby service's. Will notify Jason Marsh on my findings. I have spoke to the owner at no-29 Bayview rd & he did report the leak awhile ago. I gave him a calling card. [FT] [SSf0010] [8/1/2025 14:38] [ON SITE] Arrived back on site & water is still coming out of the road opp no-3 Charlesworth st & the n/strip at no-1 Waller Pl. I then went to do some more leak detection & got diverted to another job. [Marsh,Jason] [9/1/2025 07:43] [OFF SITE] Team, Spent the last 2 days checking storm water drains and walking streets sounding services around Waller Pl and BAYVIEW ROAD. Checked WR174 water tank site and all Air valves hydrants ect. I thought I found a good leak, water coming to surface at presser, after probing. Tested at EC 500 and after 10 minuets stopped. It was a backed-up Agi pipe. Hayden and Eathen from operation also assisted checking surveying for leaks yesterday, correlating some sections of the water pipe. Detection services are on site surveying zone from BAYVIEW ROAD up. Took sample on storm water pit outside 6 Waller Pl as requested by Charles, it had a site EC reading over 600. Dropped sample at ALS. Will get results today. Note: this storm water drain has been sampled previously 30-12-24 before repair to water main on Bayview. It still has a good flow 10l per minute, see attached. [Castle,Ken] [9/1/2025 16:09] [OFF SITE] Pulse case 08556065 raised. [FT] [SSf0010] [13/1/2025 11:10] [ON SITE] Arrived on site & water has now stop seeping across the road at no-1 Waller Pl & the front lawn at the fence at no-1 is now not pooling & starting to dry out but water is still coming out of the middle of the road at no-3 Charlesworth st. [Selliah,Sam] [14/1/2025 17:56] [OFF SITE] Caller Debbie Lightfoot from 34 Coburn Ave advised she is currently in the middle of a new build and there is water sitting all over the front. Said she was concerned about the foundations to the property. I have advised customer after discussing this further that we are doing daily tests here and it is still found to be ground water. Council have also been on site. Advised customer to take this up with the council. Looks like she has called several times previously as she was aware of where all the leaks were and testing done. Caller is on PH: 0407

497 302. [Lewis,Amanda] [15/1/2025 12:54] [OFF SITE] Resident from 2 Henry crt McCrae asking for job number of investigation here : 0416269635 - have passed on JN and adv to call if any questions - 0416269635 (Leisha Levic) [FT] [SSf0061] [17/1/2025 19:15] [ON SITE] Arrived on site & picked up no sounds on service's where the temp main is set up in View Point rd on the South side of the road. The North side has temp fencing right along it. I then walked along Prospect Hill rd & picked up no sounds. The house at no-7 has a grated drainage pit near the meter & water is constantly following. I tested the water a few times & got readings of around 400. The water is too murky to do a powder test. [FT] [SSf0061] [18/1/2025 14:07] [ON SITE] Doing leak detection & got called away to do a P-3 stop tap in Rosebud. [FT] [SSf0061] [18/1/2025 14:54] [ON SITE] Have picked up small sounds on the service to no-13 & no-15 Outlook rd [FT] [SSf0061] [18/1/2025 16:25] [ON SITE] Going to job around the cnr to turn of 5 stop taps on job no-1301713/005 as per Declan from SEW. [FT] [SSf0061] [18/1/2025 17:44] [ON SITE] Water is still seeping out of the middle of the d/way at no-29 Bayview rd & the ground has subsided beside the d/way at no-29 after hydro was used during the week. I have staked off the area & will come back later to backfill. Have notified the owners & the f/plug lugs at no-39 Bayview rd & sticking too high & the lid can't close. I have put in an action req to get that fixed. A task 008 has been created to put on more photo's. I sounded along Outlook rd & Bayview rd & Arthurs ave & was not able to pick up any sounds on the properties I could get into or any f/plugs or valves. Will sound the rest tomorrow & I am going back to Green's rd to get bags of topsoil for the subby at no-29 Bayview rd. [FT] [SSf0061] [18/1/2025 18:34] [WORKING OFF SITE] No bags of topsoil at Green's rd. Going to Lynbrook yard. [FT] [SSf0061] [18/1/2025 19:00] [WORKING OFF SITE] Picked up bags of topsoil from the Lynbrook store. [FT] [SSf0061] [19/1/2025 13:32] [ON SITE] Photo's for the last few days are on task-008 [FT] [SSf0061] [19/1/2025 13:35] [ON SITE] Arrived back on site & went to no-29 Bayview rd & removed the stakes & put 5 bags of topsoil in the subby beside the d/way. [FT] [SSf0061] [19/1/2025 14:50] [ON SITE] Sounded The Boulevard & the rest of Bayview rd & was unable to pick up any sounds to the properties I could get into. The f/plug at no-54 The boulevard is buried. I have put in an action req to get that located & raised. [FT] [SSf0061] [19/1/2025 17:29] [ON SITE] Sounded f/plugs & valves & service's in Waller Pl & Coburn ave & Charlesworth st & Henry crt & Cornell st & was not able to pick up any sounds. [FT] [SSf0061] [19/1/2025 17:37] [ON SITE] Where the water was coming out of the middle of the road opp no-3 Charlesworth ave has stopped. Looks like the council have put in a drainage pipe from the middle of the road to the grated drain in the gutter. The road has been reinstated. [FT] [SSf0061] [4/3/2025 13:30] [OFF SITE] As per M-spicer. Close the job off.

Caller Details:sss

Request Details:Wall, As discussed, please continue with the LEAK investigations, checking any SEW asset in the area. Note samples returned positive result for storm water pit. Questionable on road leaks

Action Taken :Water Network - Leak Detection - Investigation

Task CCT:Water Network - Leak Detection - Leak Investigation

TaskSummary

Failure Details:0 Not Applicable - Not Applicable - Not Applicable
Task Priority:10 30/06/2025 17:00
Is Chargeable:No
Is Pending:No
Is Cancelled:No
Is Component Type:No
PO Department:Water Maintenance
PO Supervisor:
Contractor:ServiceStream
Created By:Marsh, Jason
Department:ServiceStream Water
Supervisor:Corrin,Jason
Allocatee:
Task Status:CLOSED

Asset List

Asset	Asset Name	Parent	SI Present?
-------	------------	--------	-------------

Allocatee History

Allocatee Name	Current	Primary
SSf0010	N	Y
SSf0061	N	Y

SI List

SI Name	Rec
---------	-----

Task Number:1295094/007
Task Story:[Derwent,Ascher] [27/3/2025 09:16] Incorrect invoice in attachments? [Spicer,Michael] [27/3/2025 11:46] Invoice is just on task 7 as ran out of attachments for task 6. No cost associated with task 7
Payment Type:
SEW Sales Code:
Contractor CostCode:
Contractor SalesCode:

Material List

Part No	Description	Supplier Contractor	Quantity	Units	Unit Price(\$)	Vehicle	Del Date	Rec Date
62054	Top Soil Bag 25L	ServiceStream	5.000	each	CIC	SSv0013	-	-

Material List (continued...)

Part No	MAC Material Included	Total(\$)
62054	No	CIC

Total Materials Cost: CIC**Labour List**

Resource ID	Resource Name	Supplier Contractor	Activity Description	Start Date/Time
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	10/02/2025 14:33
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	19/01/2025 12:53
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	19/01/2025 11:57
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	WORKING OFF SITE	18/01/2025 18:42
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	18/01/2025 18:34
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	WORKING OFF SITE	18/01/2025 18:25
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	18/01/2025 17:44
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	18/01/2025 17:05
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	18/01/2025 17:05
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	18/01/2025 14:50
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	18/01/2025 14:40
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	18/01/2025 13:22
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	18/01/2025 13:15
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	17/01/2025 18:10
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	17/01/2025 18:00
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	13/01/2025 10:53
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	13/01/2025 10:02
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	8/01/2025 14:26
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	8/01/2025 13:43
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	ON SITE	2/01/2025 17:01
SSv0013	SSv0013,1ZR1GV Toyota Hilux	ServiceStream	IN TRANSIT	2/01/2025 16:14
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	2/01/2025 16:14
LLe0049	Peters,Wally	ServiceStream	ON SITE	2/01/2025 17:01
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	8/01/2025 13:43

LLe0049	Peters,Wally	ServiceStream	ON SITE	8/01/2025 14:26
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	13/01/2025 10:02
LLe0049	Peters,Wally	ServiceStream	ON SITE	13/01/2025 10:53
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	17/01/2025 18:00
LLe0049	Peters,Wally	ServiceStream	ON SITE	17/01/2025 18:10
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	18/01/2025 13:15
LLe0049	Peters,Wally	ServiceStream	ON SITE	18/01/2025 13:22
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	18/01/2025 14:40
LLe0049	Peters,Wally	ServiceStream	ON SITE	18/01/2025 14:50
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	18/01/2025 17:05
LLe0049	Peters,Wally	ServiceStream	ON SITE	18/01/2025 17:05
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	18/01/2025 17:44
LLe0049	Peters,Wally	ServiceStream	WORKING OFF SITE	18/01/2025 18:25
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	18/01/2025 18:34
LLe0049	Peters,Wally	ServiceStream	WORKING OFF SITE	18/01/2025 18:42
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	19/01/2025 11:57
LLe0049	Peters,Wally	ServiceStream	ON SITE	19/01/2025 12:53
LLe0049	Peters,Wally	ServiceStream	IN TRANSIT	10/02/2025 14:33

Labour List (continued...)

Resource ID	End Date/Time	Hours	Est. ChargeRate(\$)	Est. CostRate(\$)
SSv0013	10/02/2025 14:33	0.00		
SSv0013	19/01/2025 17:37	4.73		
SSv0013	19/01/2025 12:53	0.93		
SSv0013	18/01/2025 19:00	0.30		
SSv0013	18/01/2025 18:42	0.13		
SSv0013	18/01/2025 18:34	0.15		
SSv0013	18/01/2025 18:25	0.68		
SSv0013	18/01/2025 17:44	0.65		
SSv0013	18/01/2025 17:05	0.00		
SSv0013	18/01/2025 16:25	1.58		
SSv0013	18/01/2025 14:50	0.17		
SSv0013	18/01/2025 14:07	0.75		
SSv0013	18/01/2025 13:22	0.12		
SSv0013	17/01/2025 19:15	1.08		
SSv0013	17/01/2025 18:10	0.17		
SSv0013	13/01/2025 11:10	0.28		
SSv0013	13/01/2025 10:53	0.85		
SSv0013	8/01/2025 14:39	0.22		
SSv0013	8/01/2025 14:26	0.72		
SSv0013	2/01/2025 17:56	0.92		
SSv0013	2/01/2025 17:01	0.78		
LLe0049	2/01/2025 17:01	0.78		
LLe0049	2/01/2025 17:56	0.92		
LLe0049	8/01/2025 14:26	0.72		
LLe0049	8/01/2025 14:39	0.22		
LLe0049	13/01/2025 10:53	0.85		
LLe0049	13/01/2025 11:10	0.28		
LLe0049	17/01/2025 18:10	0.17		
LLe0049	17/01/2025 19:15	1.08		
LLe0049	18/01/2025 13:22	0.12		

CIC

LLe0049	18/01/2025 14:07	0.75	<div>CIC</div>
LLe0049	18/01/2025 14:50	0.17	
LLe0049	18/01/2025 16:25	1.58	
LLe0049	18/01/2025 17:05	0.00	
LLe0049	18/01/2025 17:44	0.65	
LLe0049	18/01/2025 18:25	0.68	
LLe0049	18/01/2025 18:34	0.15	
LLe0049	18/01/2025 18:42	0.13	
LLe0049	18/01/2025 19:00	0.30	
LLe0049	19/01/2025 12:53	0.93	
LLe0049	19/01/2025 17:37	4.73	
LLe0049	10/02/2025 14:33	0.00	

Total Charge Rate: CIC

Total Cost Rate:0

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price (\$)
SS1000	General Contractor Claim	General Claim	ServiceStream	1.000	each	CIC

Contractor Claims List (continued...)

Claims Code	Total(\$)
SS1000	CIC

Contractor Claims List

Service Code	Description	Quantity	Units	Unit Price(\$)	Total(\$)
--------------	-------------	----------	-------	----------------	-----------

Total Claims Cost: CIC

Chargeable Items

Item Code	Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)
-----------	-------------	---------------------	----------	-------	-----------------	-----------

Total Chargeable Cost:

Total Services Cost:

Task Cost Scheme:T&M

Is Extra Travel Authorised:No

UTA Item:

Labour Cost:

Vehicle Cost:

Plant Cost:

Materials Cost:

Sub-Total:

Travel Adjustment:

Actual Adjustment:

Adjusted Sub Total:

Risk Events Sub-Total Cost:
Risk Events Sub-Total Cost:
Non-UTA Materials Cost:
Total Cost:
Total Cost:
UOM Value:
Total Quantity:
AAC / ARC:
MAC / MRC Value:
Service Call Cost:
Quoted Cost:
T&M Labour Cost: CIC
T&M Vehicle Cost: CIC
T&M Plant Cost: CIC
T&M Sub-Total: CIC
T&M Travel Adjustment: CIC
T&M Actual Adjustment: CIC
T&M Adjusted Sub Total: CIC
T&M Material Cost: CIC
T&M Total Cost: CIC
SEW Labour Cost: CIC
SEW Vehicle Cost: CIC
SEW Plant Cost: CIC
SEW Materials Cost: CIC
SEW Sub-Total:
SEW Total Contractor Claims: CIC
MSF Cost: CIC
Total SEW Cost: CIC
Provisional Contractor Claims: CIC

WSI Details

Task Id	WSI Id	Planned Start	Actual Start	Planned Finish	Actual Finish	Emergency	Prop Count
---------	--------	---------------	--------------	----------------	---------------	-----------	------------

WSI Details (continued...)

Task Id	WSI Status
---------	------------

Task Number:1295094/007

Task Events

Task Event	Event Date Time	Is Key Event	Allocatee	Is Primary	Is Onsite	Is Work	Is Auto
CLOSED	5/04/2025 18:02	Yes	-	-	No	No	Yes
CHECKED	1/04/2025 14:15	Yes	-	-	No	No	Yes
DATA COMPLETE	27/03/2025 11:47	Yes	-	-	No	No	Yes

REJECTED	27/03/2025 09:16	Yes	-	-	No	No	Yes
WORK COMPLETE	4/03/2025 13:30	Yes	-	-	No	No	Yes
WORKING OFF SITE	18/01/2025 18:25	Yes	-	-	No	Yes	Yes
ON SITE	2/01/2025 17:01	Yes	-	-	Yes	Yes	Yes
IN TRANSIT	2/01/2025 16:14	Yes	-	-	No	Yes	Yes
ALLOCATED	2/01/2025 12:52	Yes	-	-	No	No	Yes
AWARDED	2/01/2025 12:52	Yes	-	-	No	No	Yes


































3 Jan 2025 11:12:02 am
38.34754873998463S 144.93807205930352E
3 Charlesworth Street
McCrae
Mornington Peninsula Shire
Victoria