

Montage Task Number	Action Taken Category – Class - Type	Department	Date Created	a. a description of any roadworks or excavation work performed by SEW, including the purpose and outcome of such works;	b. the location of the works.	c. the date those works were performed; and	d. any photographs depicting the works themselves or the location before and after the works were performed.
1257607/001	Water Network – Service Pipe – Repair of Service Pipe	Downer Water	19/07/2024 12:27	Purpose: - Customer request for bubbling water leaking out near tree within property line. Outcome: - Inspected on 19/7/2025 to confirm scope of works. Hydro excavation and repaired a leak on the ferrule for the service pipe connection in nature strip.	8 WALLER PLACE, MCCRAE VIC 3938	22/7/2024 – 26/7/2024	See folder 1257607-001 for Montage extract.
1342362/001	Water Network – Service Pipe – Repair of leak	ServiceStream Water	8/05/2025 12:11	Purpose: - Customer call advising heavy flow of water coming up through roadway filling both gutters. Outcome: - Service pipe ferrule in nature strip located and isolated. Temporary service pipe set up from No 42 Coburn to No 40 Coburn, and new task (1342362/002) created for service pipe renewal.	42 COBURN AVENUE, MCCRAE VIC 3938	8/5/2025	See folder 1342362-001 for Montage extract.
1345273/001	Water Network – Water Main – Repair of burst in nature strip	ServiceStream Water	20/05/2025 12:55	Purpose: - Damaged valve on nature strip caused by digging Outcome: - Repaired water main burst in nature strip due to unused ferrule on main and encased in concrete from stormwater pit being pulled out by plumbers undertaking drainage works trying to connect into the storm water pit.	52 COBURN AVENUE, MCCRAE VIC 3938	20/5/2025	See folder 1345273-001 for Montage extract.
1345273/002	Roadworks - Work Area - Topsoil	ServiceStream Water	21/05/2025 06:20	Purpose: - 1/2m top soil required to cover nature strip after works completed on Task 001 Outcome: - topsoil and grass seed added to the area of works	52 COBURN AVENUE, MCCRAE VIC 3938	27/5/2025	See folder 1345273-002 for Montage extract.
1345218/001	Water Network - Meter - Repair of leak	Downer Water	20/05/2025 10:17	Purpose: - New digital meter is reporting a noise that could be a leak. Outcome: tightened meter connection which had a small drip. Also dug on the naturestrip to check the service and the ground was dry with no leaks evident	20 COBURN AVENUE, MCCRAE VIC 3938	20/5/2025	See folder 1345218 for Montage extract
1301713/006	Water Network - Water Supply - Restore supply	ServiceStream Water	14/02/2025 16:34	Purpose: To flush and recharge water main in View Point Road that had been shut off so that customers who were allowed to return to their properties had water supply. Outcome: The water main was recharged and flushed into the drain at the end of View Point Road (following receipt of Council approval). During the recharge process it was noted that the isolating valve (not specifically referred to, or recorded, but deduced to be Valve ID 362909 as this is the valve that was used to isolate the main, and is the only valve in View Point Road) was leaking from the spindle. This valve was tightened up, operated and found to no longer be leaking.	10-12 VIEW POINT ROAD, MCCRAE VIC 3938	15/2/2025	See folder 1301713 for Montage extract