Request ID 2587318 Mornington Peninsula Shire As at: 16-Apr-25 09:50 AM

Type. Water - Shire Stormwater Drainage Network - SLR - Cleaning & Blockages

FINALISED

Customer Information

Mornington Peninsula Property Group Bianca

Customer: 195 Bayview Road Map:158 J12

MCCRAE 3938 (X Coord: -38.358451458333 Y Coord: 144.924508191667)

Home Phone: Personal Information

Work Phone: Mobile Phone:

eMail: Personal Information

FAX:

Property No: 12532

Linked To: 2543083

Request Information

Centre: Mornington Peninsula Shire

Received Via: Telephone
Input Officer: Cook, Kaylene

Received On: 19-Jul-23 @ 12:04 PM

Priority: P3 – 5 Days

Provider: Shire

Issue Type: Standard Request
Responsible: SIMS Roads, Team

Reference No:

Additional Names Additional Address

Primary: 195 Bayview Road MCCRAE 3938 (Prop. No: 12532, X Coord:

-38.358451458333Y Coord: 144.924508191667) Map 158 J12

Additional Information

How Received: Telephone
Safer Local Roads have No

been called:

Urgent warning signage: No

**********Customer Response Management******

Does customer wish to be

contacted:

Yes

Request Details:

Property Manager has called through to advise that there is water pooling out the front of the 195 Bayview Rd, McCrae. It is muddy all the time and especially bad when rains. Council have drainage network and pit out the front of the property. Please inspect for blocked or damaged pipe. Please contact Bianca to advise time frame and schedule on 0359868188.

19-Jul-23 @ 12:04 PM Request Created

19-Jul-23 @ 12:04 PM Action ID: 5091707 (Closed)

Assigned to: SLR SIMS Cleansing Incoming Actions Task given: Accept & Assign This Request for Team Action was due 20-Jul-23 @ 12:04 PM and was completed 19-Jul-23 @ 01:39 PM.

Action taken: Assigned Action by: Larsen Rachel

19-Jul-23 @ 12:06 PM Notification

Sent to SLR SIMS Cleansing Incoming Actions (Action)

Comment note sent by Cook Kaylene

Message: Request Comment made by Cook Kaylene SEW have referred this case back to Council for inspection

of the pits around this property - ongoing issue,

19-Jul-23 @ 01:39 PM Notes Comment by Larsen Rachel

19/7/2023 Printed for inspection

Rachel Larsen

19-Jul-23 @ 12:06 PM General Comment

Cook Kaylene

SEW have referred this case back to Council for inspection of the pits around this property - ongoing issue,

19-Jul-23 [@] 12:06 PM **Notification**

Sent to SIMS Roads Team (Responsible)

Ν

Message: Request Comment made by Cook Kaylene SEW have referred this case back to Council for inspection of the pits around this property - ongoing issue, Request ID 2587318 Mornington Peninsula Shire As at: 16-Apr-25 09:50 AM

Type. Water - Shire Stormwater Drainage Network - SLR - Cleaning & Blockages

FINALISED

19-Jul-23 @ 01:39 PM Action ID: 5091863 (Closed)

Assigned to: Cleaning & Blockages Supervisor Task given: Investigate & Respond To Customer Action was due 02-Aug-23 @ 01:39 PM and was completed 25-Jul-23 @ 07:59 AM.

Action taken: Completed - No Further Action Req Action by: Larsen Rachel 19-Jul-23 @ 01:39 PM Notification Sent to Cleaning & Blockages Supervisor (Action) Notified note sent by Larsen Rachel (Automatically) Message: Email generated for Action: 5091863 for Cleaning & Blockages Supervisor

25-Jul-23 @ 07:59 AM Notes Comment by Larsen Rachel 24/7/2023 CS attended site and found system clear. Last cleaned on 19th April 2023 refer SR2557303. CS spoke with Shirana at customer's office via phone at 10.45 a.m. and advised same. NFA required.

Rachel Larsen