General Enquiry

Request Summary

Reference Id:	2023-014394
Tracking Number:	2023-014394.RDA
Received:	27-Nov-2023 10:34:23
Priority:	Medium
Status:	Inactive
Stage:	Completed
Address:	20 Cairn Road MCCRAE VICTORIA 3938
Detail:	Customer requesting a call back to discuss some concerns with the application, specifically the storm water drainage. Customer is neighbour (18) to the applican - Peter -
Categorisation	
Request Type	Community and Stakeholder Relations Management
Request Category	Customer Service Operations

Request Category	Customer Service Operation
Request Sub Category	General Enquiry

Stage Updates

Stage
Completed
In Progress
New Request

Resolution

Date Resolved		
13-Dec-2023 13:54:57		

Resolution Resolved by Contractor

Resolution Details

Spoke to Peter, we agreed I could pass on specs of his retaining wall to neighbouring application and get the applicant to indicate the location of that wall on the site plan.