Stormwater Drainage Concern

Request Summary

2024-105410 Tracking Number: 2024-105410.BNY 16-Dec-2024 17:45:52 Received:

Urgent Priority: Status: Active

Awaiting Inspection

Address: 2 Penny Lane MCCRAE VICTORIA 3938 Refer Macrae Nov 2022 land slip Penny lane Macrae Detail:

Spoon drains at the end of Penny lane once again full of water :, we have had little rain $% \left(\frac{1}{2}\right) =\frac{1}{2}\left(\frac{1}{2}\right) =\frac{1}{2$

Categorisation

Request Type Environment Management

Flood and Stormwater Management Request Category Request Sub Category Stormwater Drainage Concern

Stage Updates

Date Completed Stage

17-Dec-2024 Awaiting Inspection 16-Dec-2024 New Request