

Road Maintenance

Request Summary

Reference Id:	2024-107126
Tracking Number:	2024-107126.IKR
Received:	21-Dec-2024 11:01:17
Priority:	Medium
Status:	Inactive
Stage:	Completed
Address:	3 Charlesworth Street MCCRAE VICTORIA 3938
Additional Location Details:	3 Charlesworth St, McCrae VIC 3938, Australia
Detail:	Bad water in middle of the narrow road, plastic bollards around leak making it difficult to pass. Been like this for weeks.

Categorisation

Request Type	Transport Connections
Request Category	Road Network
Request Sub Category	Road Maintenance

Stage Updates

Date Completed	Stage
23-Dec-2024	Completed
21-Dec-2024	New Request

Resolution

Date Resolved	Resolution	Resolution Details
23-Dec-2024 16:52:01	Resolved by Contractor	3 Charlesworth St McCrae water leak is being maintained by SEW. Please refer to reference number 129509/00123 for further updates. Thank you for your request.