
Leak Report



Unit 3, 48 Armstrong Road McCrae Victoria 3938 Australia





Comments

Arrived onsite, no one home. Meter spinning around, sounded garden tap at front of unit 3, no noise.

Called **I&S** . **I&S** Arrived gained access to rear of property, sounded rear garden tap, picked up small noise. Tightened tap & noise stopped. Sounded fittings up sideway..no other noises.

Checked meter again & meter stopped spinning...no noise.

Informed I&S of my findings & that rear garden tap may have been used & not turned off fully/left o g for a long period of time .

Photo



