

Request ID	2545864	Mornington Peninsula Shire	As at: 16-Apr-25 09:46 AM
Type.	Furniture - Outdoor - Utilities - Roadside Plant - South East Water Infrastructure		COUNT ONLY

Customer Information**Irrelevant & Sensitive**

Customer: 36 Arthurs Avenue Map:159 C10 Local Access C
 MCCRAE 3938 (X Coord: -38.35239395 Y Coord: 144.942224508334)

Home Phone:**Work Phone:****Mobile Phone:****eMail:****FAX:****Property No:** 120125**I & S****Request Information****Centre:** Mornington Peninsula Shire**Received Via:** Telephone**Input Officer:** Winther, Naomi**Received On:** 02-Mar-23 @ 11:26 AM**Priority:** P3 – 5 Days**Provider:** Shire**Issue Type:** EXEC - Executive Action Request**Responsible:** Winther, Naomi**Reference No:****Additional Information****How Received:** Telephone**Request Details:**

Customer called through to advise that sink hole has formed on RR between 38 and 40 Arthurs Ave, McCrae in align with the sink hole that has formed at the back of her property at 36 Arthurs Ave, McCrae Her property at the back and has SEW drainage in her easement. 32 Arthurs Avenue, McCrae also has been inundated with water at the back of their property. S/W with roads and confirmed to report to SEW straight away. Called through to SEW and advised will be inspected within 24 hours and Barbara contacted on the mobile. SEW reference 1128066,

02-Mar-23 @ 11:26 AM **Request Created**