

Stormwater Drainage Concern

Request Summary

Reference Id: 2024-105410
Tracking Number: 2024-105410.BNY
Received: 16-Dec-2024 17:45:52
Priority: Urgent
Status: Active
Stage: Awaiting Inspection
Address: 2 Penny Lane MCCRAE VICTORIA 3938
Detail: Refer Macrae Nov 2022 land slip Penny lane Macrae

Spoon drains at the end of Penny lane once again full of water ;,we have had little rain

Categorisation

Request Type Environment Management

Request Category Flood and Stormwater Management
Request Sub Category Stormwater Drainage Concern

Stage Updates

Date Completed	Stage
17-Dec-2024	Awaiting Inspection
16-Dec-2024	New Request