

Stormwater Drainage Concern

Request Summary

Reference Id:	2024-106738
Tracking Number:	2024-106738.MAO
Received:	20-Dec-2024 07:53:40
Priority:	Urgent
Status:	Inactive
Stage:	Completed
Address:	1 Charlesworth Street MCCRAE VICTORIA 3938
Detail:	Caller Reporting A Large Amount Of Groundwater Streaming Out Of The Road At This Location. Caller Reports South East Water Have Attended And Confirmed It Isn't A Burst Main. Caller Advises It Is A Danger To Residents And Public, As This May Be Unstable Ground, And This Is The Only Passage Out For Some Residents.

Categorisation

Request Type	Environment Management
Request Category	Flood and Stormwater Management
Request Sub Category	Stormwater Drainage Concern

Stage Updates

Date Completed	Stage
31-Dec-2024	Completed
20-Dec-2024	Awaiting Inspection
20-Dec-2024	New Request

Resolution

Date Resolved	Resolution	Resolution Details
31-Dec-2024 10:59:48	Resolved by Contractor	Roads Corridor Team attended 1 Charlesworth St McCrae on 20th December & made area safe. No Shire assets at location. South East Water has been contacted via phone for re-inspection of pipes.