Task Number :1243555/001
Task Address: 47 AUSTIN AVENUE, MCCRAE VIC 3938 MapRef: 170K3
Program Name:
Task Work Type:Planned Maintenance - Repair
Source Of Work:
Facility:
Permit Not Required:No
Permit Pre Approved:No
Permit Reason:Other
Permit Other Reason:
Task Story: PI [25/5/2024 13:34] [AWARDED] Property Number: 02E//00490/39 [Springs Michelle] [25/5/2024 14:09]
Property Number:02E//00490/39 [Springs,Michelle] [25/5/2024 14:09]
[AWARDED] Checked [FT] [SSf0004] [26/5/2024 15:07] [ON SITE] Arrived on
site set up site made safe then loctaed meter at edge of driveway/fenceline in
the bushes. good noise on service meter was ticking over. shut off and
resounded noise and leak stopped. spoke with neigbour he said that customer
is currently away and no one is home but he will pass on a message. issued
red notice with 7 days left safe [FT] [SSf0004] [26/5/2024 15:10] [ON SITE] red
notice num #00358 [Lewis,Amanda] [27/5/2024 16:19] [DATA COMPLETE]
Owner Craig has called, leak has been repaired, has asked to be put thru to
accounts to apply for leak adjustment on next bill - PI
Caller Details:Dave, PI
Request Details:seepeing water through servie pipe, not alot of water, no
acsess issues no animals
Action Taken :Water Network - Service Pipe - Inspection
Task CCT:Water Network - Service Pipe - Repair of leak
Failure Details: 0 Not Our Asset - Not Our Asset - Not Our Asset
Task Priority:7 1/06/2024 13:34
Is Chargeable:No
Is Pending:No
Is Cancelled:No
Is Component Type:No
PO Department:Water Maintenance
PO Supervisor:
Contractor:ServiceStream
One of all D

Created By PI
Department:ServiceStream Water

Supervisor: Griffith, Jason

Allocatee:

Task Status:CLOSED

Asset List

Asset	Asset Name	Parent	SI Present?
1050173019	1050173019	-	N

Allocatee History

Allocatee Name	Current	Primary
SSf0004	Ν	Υ

SI List

SI Name	Rec
Red Notice	No

Task Number: 1243555/001

Task Story:
Payment Type:
SEW Sales Code:
Contractor Cost Co

Contractor CostCode: Contractor SalesCode:

Material List

Part Description S	Supplier Quantity	Units Unit Price(\$)	Vehicle	Del Date	Rec Date
--------------------	-------------------	----------------------	---------	-------------	-------------

Material List (continued...)

Total Materials Cost:

Labour List

Resource ID	Resource Name	Supplier Contractor	Activity Description
LLv0278	LLv0278,XV 22FI Hino 500 Supertruck	ServiceStream	ON SITE
LLv0278	LLv0278,XV 22FI Hino 500 Supertruck	ServiceStream	IN TRANSIT
LLe0496	Simons,Zac	ServiceStream	IN TRANSIT
LLe0496	Simons,Zac	ServiceStream	ON SITE

Labour List (continued...)

- 10 0 0 0 11 0 0	Start Date/Time	End Date/Time	Hours	Est. ChargeRate (\$)	Est. CostRate (\$)
LLv0278	26/05/2024 14:39	26/05/2024 15:10	0.52		
LLv0278	26/05/2024 14:07	26/05/2024 14:39	0.53		
LLe0496	26/05/2024 14:07	26/05/2024 14:39	0.53		
LLe0496	26/05/2024 14:39	26/05/2024 15:10	0.52		_

Total Charge Rate: CIC
Total Cost Rate

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price(\$)
ss1000	General Contractor Claim	General Claim	ServiceStream	1.000	each	CIC

Contractor Claims List (continued...)

	Claims Code	Total(\$)
l	ss1000	CIC

Contractor Claims List

Service Code	Description	Quantity	Units	Unit Price(\$)	Total(\$)

Total Claims Cost CIC

Chargeable Items

Item Code Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)
-----------------------	------------------------	----------	-------	--------------------	-----------

Total Chargeable Cost:

Total Services Cost:

Task Cost Scheme: Service Call Is Extra Travel Authorised: No

UTA Item:
Labour Cost:
Vehicle Cost:
Plant Cost:
Materials Cost:
Sub-Total:

Travel Adjustment: Actual Adjustment: Adjusted Sub Total:

Risk Events Sub-Total Cost: Risk Events Sub-Total Cost:

Non-UTA Materials Cost:

Total Cost:
Total Cost:
UOM Value:
Total Quantity:
AAC / ARC:

MAC / MRC Value:

Service Call Cost CIC

Quoted Cost:

T&M Labour Cost:

T&M Vehicle Cost:

T&M Plant Cost:

T&M Sub-Total:

T&M Travel Adjustment:

T&M Actual Adjustment:

T&M Adjusted Sub Total:

T&M Material Cost:

T&M Total Cost:

SEW Labour Cost CIC

SEW Vehicle Cost CIC

SEW Plant Cost CIC

SEW Materials Cost CIC

SEW Sub-Total:

SEW Total Contractor Claims CIC

MSF Cost: CIC

Total SEW Cost CIC

Provisional Contractor Claims CIC

WSI Details

Task	WSI	Planned	Actual	Planned	Actual	Emergency	Prop
ld	ld	Start	Start	Finish	Finish		Count

WSI Details (continued...)

Task Id WSI Status

Task Number: 1243555/001

Task Events


Task Event	Event Date Time	Is Key Event	Allocatee	Is Primary	ls Onsite	ls Work	ls Auto				
CLOSED	11/06/2024 18:13	Yes	 -	-	No	No	Yes				
CHECKED	27/05/2024 18:21	Yes	-	-	No	No	Yes				
DATA COMPLETE	27/05/2024 06:45	Yes	-	_	No	No	Yes				
WORK COMPLETE	26/05/2024 15:10	Yes	-	-	No	No	Yes				
ON SITE	26/05/2024 14:39	Yes	-	-	Yes	Yes	Yes				
IN TRANSIT	26/05/2024 14:07	Yes	-	-	No	Yes	Yes				
ALLOCATED	25/05/2024 23:28	Yes	-	-	No	No	Yes				
AWARDED	25/05/2024 13:34	Yes	-	-	No	No	Yes				

Types: Leaking from meter to house

Howlssued: Notice left in letter box

DaysToRepair: 7

FollowUpNotes: cusomter is not home on holidays







Reference number 1243555/601

Address 47 AUSTIN AV

Postcode 3938 Hello. A water leak has been found on this property at one or more of these assets: internal service pipe other What this means for you These assets aren't included in our maintenance program because they're part of the private plumbing

SEW 0001 0001 4988 0009

system that services your property.

If you're an owner occupier – it's your responsibility

to maintain these service pipes and fittings.

If you're a tenant – please inform the owner and/ or property manager of this notice. You may need to confirm your responsibilities to the property with your

landlord/property manager.