Task Number: 1161272/001

Task Address: 1 FAIRWAY CRESCENT, MCCRAE VIC 3938 MapRef: 170K2

**Program Name:** 

Task Work Type: Planned Maintenance - Repair

Source Of Work:

Facility:

Permit Not Required:No Permit Pre Approved:No Permit Reason:Other Permit Other Reason:

**Task Story**:[Ludewig,Ralph] [19/7/2023 13:29] [ALLOCATED] Checked D [FT ] [LLf0051] [19/7/2023 15:11] [ON SITE] on site 20mm meter buried water pushing up from around it seeping access ok no pne home [Moser,John] [19/7/2023 17:56] [OFF SITE] as per crew Task No: 1161272/001 Old Task CCT: Water Network - Water Main - Repair of leak in other location New Task CCT: Water Network - Service Pipe - Repair of leak Old Priority No: 5 New Priority No: 7 [FT ] [LLf0006] [20/7/2023 10:37] [ON SITE] Dug out meter to find leak on garden standpipe.Issued 7 day red notice.

Caller Details:vanessa PI - leak on the street side of the meter as confirmed by customer - water pooling around - no access issues - no dogs short side of mains

**Action Taken**: Water Network - General - Red Notice Issued **Task CCT**: Water Network - Service Pipe - Repair of leak

Failure Details: 0 Not Applicable - Not Applicable - Not Applicable

Task Priority:7 26/07/2023 13:00

Is Chargeable:No Is Pending:No Is Cancelled:No

Is Component Type:No

PO Department: Water Maintenance

PO Supervisor:

**Contractor**:ServiceStream **Created By**:Perera, Achala

**Department**:ServiceStream Water

Supervisor: Griffith, Jason

Allocatee:

Task Status:CLOSED

#### **Asset List**

Asset A	sset Name	Parent	SI Present?
---------	-----------	--------	-------------

#### Allocatee History

Allocatee Name	Current	Primary

SSf0049	Ν	Υ
LLf0051	Ν	Υ
LLf0006	N	Υ

# SI List

SI Name	Rec
Red Notice	No

Task Number: 1161272/001

Task Story:
Payment Type:
SEW Sales Code:
Contractor CostCode:
Contractor SalesCode:

# **Material List**

Part		Supplier Contractor				
IAO	_	Contractor	_	Luce(2)	Date	Date

# **Material List (continued...)**

Part No	MAC Material Included	Total(\$)
II air iso	MAO Material Included	ι Οται(Ψ)

**Total Materials Cost:** 

# **Labour List**

Resource ID	Resource Name	Supplier Contractor	Activity Description	Start Date/Time
LLv0232	LLv0232,1MP 2IR Holden Colorado	ServiceStream	ON SITE	20/07/2023 09:58
LLv0232	LLv0232,1MP 2IR Holden Colorado	ServiceStream	IN TRANSIT	20/07/2023 09:19
LLv0250	LLv0250,1NT 9KY Holden Colorado	ServiceStream	ON SITE	19/07/2023 15:10
LLv0250	LLv0250,1NT 9KY Holden Colorado	ServiceStream	IN TRANSIT	19/07/2023 14:22
LLe0044	McLenaghan,Steven	ServiceStream	IN TRANSIT	20/07/2023 09:19
LLe0044	McLenaghan,Steven	ServiceStream	ON SITE	20/07/2023 09:58
LLe0249	Patterson,Daniel	ServiceStream	IN TRANSIT	19/07/2023 14:22
LLe0249	Patterson,Daniel	ServiceStream	ON SITE	19/07/2023 15:10

**Labour List (continued...)** 

Resource ID	End Date/Time	Hours	Est. ChargeRate(\$) Est. CostRate(\$)
LLv0232	20/07/2023 10:38	0.67	
LLv0232	20/07/2023 09:58	0.65	
LLv0250	19/07/2023 15:25	0.25	
LLv0250	19/07/2023 15:10	0.80	

LLe0044	20/07/2023 09:58	0.65	
LLe0044	20/07/2023 10:38	0.67	
LLe0249	19/07/2023 15:10	0.80	CIC
LLe0249	19/07/2023 15:25	0.25	

Total Charge Rate CIC

Total Cost Rate

#### **Contractor Claims List**

Claims Code	Description		Supplier Contractor	Quantity	Units	Unit Price(\$)
llss1000	General Contractor Claim	General Claim	ServiceStream	1.000	each	CIC

# **Contractor Claims List (continued...)**

Claims Code	Total(\$)
ss1000	CIC

# **Contractor Claims List**

Service Code Description Quantity	Units	Unit Price(\$)	Total(\$)
-----------------------------------	-------	----------------	-----------

Total Claims Cost CIC

**Chargeable Items** 

Item Code Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)	-
-----------------------	------------------------	----------	-------	--------------------	-----------	---

Total Chargeable Cost:

**Total Services Cost:** 

Task Cost Scheme: Service Call Is Extra Travel Authorised: No

UTA Item: Labour Cost: Vehicle Cost: Plant Cost: Materials Cost:

Sub-Total:

Travel Adjustment: Actual Adjustment: Adjusted Sub Total:

Risk Events Sub-Total Cost: Risk Events Sub-Total Cost:

**Non-UTA Materials Cost:** 

Total Cost: Total Cost: UOM Value: Total Quantity: AAC / ARC:

MAC / MRC Value:

Service Call Cost CIC

Quoted Cost:

**T&M Labour Cost**:

**T&M Vehicle Cost:** 

**T&M Plant Cost:** 

T&M Sub-Total:

**T&M Travel Adjustment:** 

**T&M** Actual Adjustment:

**T&M Adjusted Sub Total:** 

**T&M Material Cost:** 

**T&M Total Cost:** 

SEW Labour Cost CIC

SEW Vehicle Cost Cic

SEW Plant Cost CIC

SEW Materials Cost CIC

**SEW Sub-Total**:

SEW Total Contractor Claims: CIC

MSF Cost CIC

Total SEW Cost CIC

Provisional Contractor Claims CIC

# **WSI Details**

Task	WSI	Planned	Actual	Planned	Actual	Emergency	Prop
ld	ld	Start	Start	Finish	Finish	Emergency	Count

# WSI Details (continued...)

Task Id WSI Status

Task Number: 1161272/001

#### **Task Events**

TOOK EVOITED								
Task Event	Event Date Time	ls Key Event	Allocatee	ls Primary	ls Onsite	ls Work	ls Auto	
CLOSED	8/08/2023 18:06	Yes	-	<b> -</b>	No	No	Yes	
CHECKED	20/07/2023 18:17	Yes	-	-	No	No	Yes	
DATA COMPLETE	20/07/2023 14:24	Yes	-	-	No	No	Yes	
WORK COMPLETE	20/07/2023 10:38	Yes	-	-	No	No	Yes	
ON SITE	19/07/2023 15:10	Yes	-	-	Yes	Yes	Yes	
IN TRANSIT	19/07/2023 14:22	Yes	-	-	No	Yes	Yes	
ALLOCATED	19/07/2023 13:53	Yes	-	<b> -</b>	No	No	Yes	
AWARDED	19/07/2023 13:00	Yes	-	-	No	No	Yes	

Types: FGT

HowIssued: Notice left in letter box

DaysToRepair: 7


FollowUpNotes: Dug out meter to find leak on garden standpipe. Issued 7 day


red notice.











PrtSc SysRq

# Defective water pipes or fittings notice

Reference number 1161272

Address | FAIRWAY (DESCENT

McCase Postcode 3938

Hello.

A water leak has been found on this property at one or more of these assets:

Vinternal service pipe

O other LEAK ON STANDADE

# What this means for you

These assets aren't included in our maintenance program because they're part of the private plumbing system that services your property.

If you're an owner occupier – it's your responsibility to maintain these service pipes and fittings.

If you're a tenant – please inform the owner and/ or property manager of this notice. You may need to confirm your responsibilities to the property with your landlord/property manager.

GENERAL SERVICE ASSEMBLY

10353

# LLf0006

#### What you need to do

Please have the defective pipes or fittings repaired within:



days from receipt of this notice.

### Let us know when the repair is completed by either:



Completing the online form at s.sew.com.au/defectnotice or;



Calling our faults and emergencies team on 13 28 12, quoting the reference number on the front of this notice.

Thanks for understanding the importance of having this leak fixed quickly. If the repairs aren't completed within the time frame above, we may need to issue a legal notice under the Water Act 1989, then:

- · Enter the property to fix the defective pipes and fittings;
- · Recover from you our costs of doing the necessary work.


Issued by

Time

10000

Date 13/7/13

# Who's responsible for the pipes and fittings



- 1. South East Water we are responsible for the water meter and pipes from the street to your meter.
- 2. Property owner/tentant is responsible for the pipes from the water meter to the house.

There are variations on the above example. For more scenarios on asset responsibility visit: southeastwater.com.au/assetresponsibility

# **Need more information?**

If you have questions or would like to discuss the leak, you can call us 24/7 on 13 28 12.

Interpreter service 9202 0130 (all languages) TTY users 13 36 77 (ask for 13 18 51)