Task Number: 1144259/001

Task Address: 10 CATHERINE STREET, MCCRAE VIC 3938 MapRef:

158K11

Program Name:

Task Work Type: Planned Maintenance - Repair

Source Of Work:

Facility:

Permit Not Required:No Permit Pre Approved:No Permit Reason:Other Permit Other Reason:

Task Story: [Lewis, Amanda] [12/5/2023 08:44] [AWARDED] Property Number: 02E//00430/8 [Ludewig, Ralph] [12/5/2023 08:52] [AWARDED] Checked DD [FT] [LLf0006] [12/5/2023 10:47] [ON SITE] Arrived to find tree loppers onsite and to unsafe to enter property as falling branches. I can see water seeping from paved driveway. I will try to return later to sound service. [FT] [LLf0006] [12/5/2023 14:04] [ON SITE] Found meter and slowly turning over. Turned off stop tap and leak started to dry up in paved driveway. Issued 7 day red notice.

Caller Details:DOM LEDWIDGE, PI 10 Catherine STREET,

MCCRAE 3938

Request Details:Water flowing steadily fom under driveway here (getting away) - meter not moving - access ok, no dogs.

Action Taken: Water Network - General - Red Notice Issued **Task CCT**: Water Network - Service Pipe - Repair of leak

Failure Details: 0 Not Applicable - Not Applicable - Not Applicable

Task Priority:4 12/05/2023 16:44

Is Chargeable:No Is Pending:No Is Cancelled:No

Is Component Type:No

PO Department: Water Maintenance

PO Supervisor:

Contractor:ServiceStream **Created By**:Lewis, Amanda

Department:ServiceStream Water

Supervisor: Griffith, Jason

Allocatee:

Task Status: CLOSED

Asset List

1			I	
	Asset	Asset Name	Parent	SI Present?

Allocatee History

Allocatee Name	Current	Primary
LLf0006	N	Υ

SI List

SI Name	Rec
Red Notice	No

Task Number: 1144259/001

Task Story:
Payment Type:
SEW Sales Code:
Contractor CostCode:
Contractor SalesCode:

Material List

Part	Doccrintion	Supplier	Quantity	Unite	Unit	Vohiclo	Del	Rec
No	Description	Contractor	Qualitity	Units	Price(\$)	Venicle	Date	Date

Material List (continued...)

Part No	MAC	Material Included	Total(\$)
---------	-----	-------------------	-----------

Total Materials Cost:

Labour List

Lanvai Li	21			
Resource ID	Resource Name	Supplier Contractor	Activity Description	Start Date/Time
LLv0232	LLv0232,1MP 2IR Holden Colorado	ServiceStream	ON SITE	12/05/2023 13:29
LLv0232	LLv0232,1MP 2IR Holden Colorado	ServiceStream	IN TRANSIT	12/05/2023 13:12
LLv0232	LLv0232,1MP 2IR Holden Colorado	ServiceStream	ON SITE	12/05/2023 10:10
LLv0232	LLv0232,1MP 2IR Holden Colorado	ServiceStream	IN TRANSIT	12/05/2023 09:47
LLe0044	McLenaghan,Steven	ServiceStream	IN TRANSIT	12/05/2023 09:47
LLe0044	McLenaghan,Steven	ServiceStream	ON SITE	12/05/2023 10:10
LLe0044	McLenaghan,Steven	ServiceStream	IN TRANSIT	12/05/2023 13:12
LLe0044	McLenaghan,Steven	ServiceStream	ON SITE	12/05/2023 13:29

Labour List (continued...)

Resource ID	End Date/Time	Hours	Est. ChargeRate(\$) Est. CostRate(\$)
LLv0232	12/05/2023 14:05	0.60	
LLv0232	12/05/2023 13:29	0.28	
LLv0232	12/05/2023 10:48	0.63	
LLv0232	12/05/2023 10:10	0.38	

TaskSummary

LLe0044	12/05/2023 10:10	0.38	
LLe0044	12/05/2023 10:48	0.63	(- (-
LLe0044	12/05/2023 13:29	0.28	UIU
LLe0044	12/05/2023 14:05	0.60	

Total Charge Rate: CIC

Total Cost Rate cic

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price(\$)
SS1000	General Contractor Claim	General Claim	ServiceStream	1.000	each	CIC

Contractor Claims List (continued...)

Claims Code	Total(\$)
SS1000	CIC

Contractor Claims List

Service Code	Description	Quantity	Unit Price(\$)	Total(\$)

Total Claims Cost CIC

Chargeable Items

				,	g		n
Item Code	Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)	

Total Chargeable Cost:

Total Services Cost:

Task Cost Scheme: Service Call Is Extra Travel Authorised: No

UTA Item: Labour Cost: Vehicle Cost: Plant Cost: Materials Cost:

Sub-Total:

Travel Adjustment: Actual Adjustment: Adjusted Sub Total:

Risk Events Sub-Total Cost: Risk Events Sub-Total Cost:

Non-UTA Materials Cost:

Total Cost: Total Cost: UOM Value: Total Quantity: AAC / ARC:

MAC / MRC Value:

Service Call Cost CIC

Quoted Cost:

T&M Labour Cost:

T&M Vehicle Cost:

T&M Plant Cost:

T&M Sub-Total:

T&M Travel Adjustment:

T&M Actual Adjustment:

T&M Adjusted Sub Total:

T&M Material Cost:

T&M Total Cost:

SEW Labour Cost CIC SEW Vehicle Cost

SEW Plant Cost CIC

SEW Materials Cost: CIC

SEW Sub-Total:

SEW Total Contractor Claims CIC

MSF Cost CIC

Total SEW Cost: CIC

Provisional Contractor Claims: CIC

WSI Details

Task	WSI	Planned	Actual	Planned	Actual	Emergency	Prop
ld	ld	Start	Start	Finish	Finish		Count

WSI Details (continued...)

Task Id WSI Status

Task Number: 1144259/001

Task Events

TON EVOITO											
Task Event	Event Date Time	ls Key Event	Allocatee	Is Primary	ls Onsite	ls Work	Is Auto				
CLOSED	8/06/2023 18:03	Yes	-	 -	No	No	Yes				
CHECKED	8/06/2023 11:07	Yes	-	-	No	No	Yes				
DATA COMPLETE	22/05/2023 22:24	Yes	-	-	No	No	Yes				
WORK COMPLETE	12/05/2023 14:05	Yes	-	-	No	No	Yes				
ON SITE	12/05/2023 10:10	Yes	-	 -	Yes	Yes	Yes				
IN TRANSIT	12/05/2023 09:47	Yes	-	-	No	Yes	Yes				
ALLOCATED	12/05/2023 08:54	Yes	-	-	No	No	Yes				
AWARDED	12/05/2023 08:44	Yes	-	_	No	No	Yes				


Types: Leaking from meter to house

Howlssued: Handed to owner

DaysToRepair: 7

FollowUpNotes: Found meter and slowly turning over. Turned off stop tap and leak started to dry up in paved driveway. Issued 7 day red notice.











LLf0006

South East :: Water ::

SEW.0001.0001.4992_0011

PrtS

SysRe

Defective water pipes or fittings notice

Reference number

1144259

Address 10

Postcode 3938

Hello,

A water leak has been found on this property at one or more of these assets:

MOCRAG

internal service pipe

) other

What this means for you

These assets aren't included in our maintenance program because they're part of the private plumbing system that services your property.

If you're an owner occupier - it's your responsibility to maintain these service pipes and fittings.

If you're a tenant - please inform the owner and/ or property manager of this notice. You may need to confirm your responsibilities to the property with your landlord/property manager.

LLf0006

What you need to do

Please have the defective pipes or fittings repaired within:



days from receipt of this notice.

Let us know when the repair is completed by either:



Completing the online form at s.sew.com.au/defectnotice or;



Calling our faults and emergencies team on 13 28 12, quoting the reference number on the front of this notice.


Thanks for understanding the importance of having this leak fixed quickly. If the repairs aren't completed within the time frame above, we may need to issue a legal notice under the Water Act 1989, then:

- · Enter the property to fix the defective pipes and fittings;
- · Recover from you our costs of doing the necessary work.


Issued by

Time





Who's responsible for the pipes and fittings



- 1. South East Water we are responsible for the water meter and pipes from the street to your meter.
- 2. Property owner/tentant is responsible for the pipes from the water meter to the house.

There are variations on the above example. For more scenarios on asset responsibility visit: southeastwater.com.au/assetresponsibility

Need more information?

If you have questions or would like to discuss the leak, you can call us 24/7 on 13 28 12.

Interpreter service 9202 0130 (all languages) TTY users 13 36 77 (ask for 13 18 51)