

Task Number:1345218/001**Task Address:**20 COBURN AVENUE, MCCRAE VIC 3938 MapRef : 159A10**Program Name:****Task Work Type:**Unknown - Investigation**Source Of Work:****Facility:****Permit Not Required:**No**Permit Pre Approved:**No**Permit Reason:**Other**Permit Other Reason:**

Task Story:[carey,Stuart] [20/5/2025 10:17] [AWARDED] Property Number:02E//00435/17 [FT] [DNf00100] [20/5/2025 11:34] [ON SITE SERVICE OK] Arrived did prestart. Found meter inside a timber box, meter has to sit on an angle as the cover will not fit otherwise. I noticed a small drip on our side of the meter, I tightened the washer coupling and no more drips, I sounded service, no noise, I dug up in N/S the otherside of the fence found service approx 800mm deep, not wet and I sounded the copper and no noise. Meter Reading never moved the whole time I was there. All seems to be OK.

Caller Details:Nwetwork Leak

Request Details:Network Leaks: meter at no, 20 has elevated AUC, no other meters in this street have the same elevation of AUC, no internal leaks either based on smart meter data, please investigate, it'll likely be a very small leak.

Action Taken :Water Network - Meter - Repair of leak**Task CCT:**Water Network - Leak Detection - Leak Investigation**Failure Details:**1 Water Meter 20mm to 25mm - Leaking - Seal Failure**Task Priority:**3 20/05/2025 13:17**Is Chargeable:**No**Is Pending:**No**Is Cancelled:**No**Is Component Type:**No**PO Department:**Water Maintenance**PO Supervisor:****Contractor:**Downer**Created By:**carey, Stuart**Department:**Downer Water**Supervisor:****Allocatee:****Task Status:**CHECKED**Asset List**

Asset	Asset Name	Parent	SI Present?
1131459624	1131459624	-	N

Allocatee History

--	--	--	--

Allocatee Name	Current	Primary
DNf00100	N	Y

SI List

SI Name	Rec
---------	-----

Task Number:1345218/001**Task Story:****Payment Type:****SEW Sales Code:****Contractor CostCode:****Contractor SalesCode:****Material List**

Part No	Description	Supplier Contractor	Quantity	Units	Unit Price(\$)	Vehicle	Del Date	Rec Date
---------	-------------	---------------------	----------	-------	----------------	---------	----------	----------

Material List (continued...)

Part No	MAC Material Included	Total(\$)
---------	-----------------------	-----------

Total Materials Cost:**Labour List**

Resource ID	Resource Name	Supplier Contractor	Activity Description	Start Date/Time
DNv0028	DNv0028,630YUU Holden Colorado	Downer	ON SITE SERVICE OK	20/05/2025 11:28
DNv0028	DNv0028,630YUU Holden Colorado	Downer	ON SITE	20/05/2025 11:03
DNv0028	DNv0028,630YUU Holden Colorado	Downer	IN TRANSIT	20/05/2025 10:36
DNe0053	Matthews,Peter	Downer	IN TRANSIT	20/05/2025 10:36
DNe0053	Matthews,Peter	Downer	ON SITE	20/05/2025 11:03
DNe0053	Matthews,Peter	Downer	ON SITE SERVICE OK	20/05/2025 11:28

Labour List (continued...)

Resource ID	End Date/Time	Hours	Est. ChargeRate(\$)	Est. CostRate(\$)
DNv0028	20/05/2025 11:35	0.12	CIC	
DNv0028	20/05/2025 11:28	0.42		
DNv0028	20/05/2025 11:03	0.45		
DNe0053	20/05/2025 11:03	0.45		
DNe0053	20/05/2025 11:28	0.42		
DNe0053	20/05/2025 11:35	0.12		

Total Charge Rate: **CIC**
 Total Cost Rate: **CIC**

Contractor Claims List

Claims Code	Description	Claim Type	Supplier Contractor	Quantity	Units	Unit Price (\$)
DN1000	General Contractor Claim	General Claim	Downer	1.000	each	CIC

Contractor Claims List (continued...)

Claims Code	Total(\$)
DN1000	CIC

Contractor Claims List

Service Code	Description	Quantity	Units	Unit Price(\$)	Total(\$)
--------------	-------------	----------	-------	----------------	-----------

Total Claims Cost: **CIC**

Chargeable Items

Item Code	Description	Supplier Contractor	Quantity	Units	Unit Price (\$)	Total(\$)
-----------	-------------	---------------------	----------	-------	-----------------	-----------

Total Chargeable Cost:

Total Services Cost:

Task Cost Scheme:UTA

Is Extra Travel Authorised:No

UTA Item:9123 - Repair of Domestic Service =25mm dia. (Above Ground)

Labour Cost: **CIC**

Vehicle Cost: **CIC**

Plant Cost: **CIC**

Materials Cost: **CIC**

Sub-Total: **CIC**

Travel Adjustment: **CIC**

Actual Adjustment: **CIC**

Adjusted Sub Total: **CIC**

Risk Events Sub-Total Cost: **CIC**

Risk Events Sub-Total Cost: **CIC**

Non-UTA Materials Cost: **CIC**

Total Cost: **CIC**

Total Cost: **CIC**

UOM Value:

Total Quantity: **CIC**

AAC / ARC: **CIC**

MAC / MRC Value: **CIC**

Service Call Cost:

Quoted Cost:**T&M Labour Cost:****T&M Vehicle Cost:****T&M Plant Cost:****T&M Sub-Total:****T&M Travel Adjustment:****T&M Actual Adjustment:****T&M Adjusted Sub Total:****T&M Material Cost:****T&M Total Cost:****SEW Labour Cost:** **SEW Vehicle Cost:** **SEW Plant Cost:** **SEW Materials Cost:** **SEW Sub-Total:****SEW Total Contractor Claims:** **MSF Cost:** **Total SEW Cost:** **Provisional Contractor Claims:** **WSI Details**

Task Id	WSI Id	Planned Start	Actual Start	Planned Finish	Actual Finish	Emergency	Prop Count
---------	--------	---------------	--------------	----------------	---------------	-----------	------------

WSI Details (continued...)

Task Id	WSI Status
---------	------------

Task Number:1345218/001**Task Events**

Task Event	Event Date Time	Is Key Event	Allocatee	Is Primary	Is Onsite	Is Work	Is Auto
CHECKED	21/05/2025 17:30	Yes	-	-	No	No	Yes
DATA COMPLETE	21/05/2025 10:26	Yes	-	-	No	No	Yes
WORK COMPLETE	20/05/2025 11:36	Yes	-	-	No	No	Yes
ON SITE SERVICE OK	20/05/2025 11:28	Yes	-	-	Yes	Yes	Yes
ON SITE	20/05/2025 11:03	Yes	-	-	Yes	Yes	Yes
IN TRANSIT	20/05/2025 10:36	Yes	-	-	No	Yes	Yes
ALLOCATED	20/05/2025 10:18	Yes	-	-	No	No	Yes
AWARDED	20/05/2025 10:17	Yes	-	-	No	No	Yes