

Task Number: 94325/005

Address: 20 THE EYRIE, MCCRAE VIC 3938

Creation Date: 4/12/2024 07:55

Request Type: Sewer Network - Creek Crossing - Inspection

Priority: 10

Initial Comments: Please carry out creek crossing inspection as per SI. Attach required photos and add comments for any issues or defects not covered in the SI form.

Action Taken: Sewer Network - Creek Crossing - Inspection

Failure Details: 0 Not Applicable - Not Applicable - Not Applicable

People onsite: Dean Kairies(at time was senior leading hand) currently a supervisor

Job Comments: [FT] [SSf0203] [30/1/2025 08:36] [ON SITE SERVICE OK]

Onsite, Creek crossing in fair condition. The u/s MH is on a very steep embankment and is more high risk to work from. Underneath the MH has been slightly undermined.

There has been a few bands put around joins that are peeling off. Refer to photos.

Looks like vegetation has been cut back where the d/s MH is located but d/s MH isnt visually accessible.